

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3161/11/24

Your Ref:

Date: 4th Nov 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00, S(048580)

Name of Insured : Mr Kwek Siew Chuan Jason
Date of Accident : 03/11/24 (19:30hrs)
Policy Number : D18MPC0003164_05

Not Allowed
in
motor
Excess?

6 days. L/S
whenever...

Estimate cost of repair to TOYOTA WISH (A) 2.0 MPV - SLT 4012 S

1 pc tail gate door	Rad 2D	\$ 2,821.30	✓
1 set rear windscreen glass seal	RM	199.80	✓
1 pc rear windscreen glass inner damper	RM	143.00	✓
1 pc rear windscreen glass sealant	RM	60.00	40 S/W
1 pc tail gate door logo emblem	RM	73.50	✓
1 pc licence lamp chrome moulding	Bullone	342.30	✓
1 pc 'Broneo Motor' emblem	RM	57.30	✓
1 pc tail gate door o/s reflector	one	315.70	✓
1 pc tail gate door handle cover	RM	31.90	✓
1 pc tail gate door inner lock	Dayle	571.50	✓
1 pc tail gate door lock stricker	11	56.70	X
1 pc tail gate door weatherstrip	RM	463.00	✓
1 pc trim board cover		503.50	?
16 pcs trim board clips	RM 3.80	60.80	X
1 pc wiper motor		1,035.30	?
1 pc top spoiler sealant	11	60.00	X
10 pcs top spoiler clips	RM 4.20	42.00	X
1 pc top spoiler damper seal	RM	38.80	✓
1 pc rear bumper	211	911.60	✓
10 pcs rear bumper clips	RM 6.00	60.00	✓
1 pc rear bumper o/s top retainer	one	70.20	✓
1 pc rear bumper o/s side retainer	one/ Bul	149.10	✓
1 pc rear bumper o/s stay bracket	RM	74.70	✓
1 set rear bumper reverse sensor	multibon	268.80	✓
1 pc rear bumper o/s reflector		83.40	?
1 pc rear exhaust muffler	R	1,823.40	X
2 pcs rear exhaust muffler mounting	RM 68.20	136.40	X
1 pc rear end panel	Rad 2D	817.70	✓
1 pc rear end panel top garnish	RM	413.40	✓
6 pcs rear end panel top garnish clips	RM 6.00	36.00	✓
1 pc rear floor board cover		999.00	?
1 pc spare tyre carrier		455.40	?
1 pc spare tyre carrier lock nut		55.30	?
1 pc rear o/s fender	R	1,652.70	X
1 pc rear o/s fender inner wheel guard	11	92.50	X
1 pc o/s tail lamp assy	RM	461.80	✓
8 pcs rear o/s fender inner shield clips	RM 6.00	48.00	✓
1 pc Luggage room box separator	one	559.30	✓

Less 25% \$ 15,645.10
\$ 3,911.28

\$ 11,733.82

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3161/11/24

Your Ref:

Date: 4th NOV 2024

M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.,

Balance B/F... \$ 11,733.82

1 pc body sealant
1 pc rear number plate

11 60.00 S.N. X
SC 45.00 S.N. 40

To wiring check up & transfer affected wiring system. camera,

100.00 30

To remove & refix rear windscreen glass & o/s quarter glass.

250.00 120

To remove & refix tail gate door hinge, shock absorber, inner lock, wiper motor, arm, trim board cover, handle & necessary parts into new door.

180.00 60

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.

150.00 80

To transfer tail gate door top spoiler & pump sealant.

11 150.00 X

To jack, straighten rear exhaust muffler & tail pipe.

180.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, rear floor board panel & necessary parts, to weld, renew & align above parts.

1,800.00 1200

To putty & respray painting on all affected accident parts.

1,600.00 1200

\$ 16,248.82

=====

Dollars : Sixteen Thousand Two Hundred Forty Eight And Eighty Two Only.

HUP MOTOR TRADING & SERVICE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: