

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24110085/EMA3Q2

Date: 03/03/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100495410

Claimant Vehicle No : SNS8789P Insured Vehicle No : SJB5786D

Date of Loss: 05/11/2024 Nature of Claim: TP Claim No: 0885966314SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNS8789P

Make & Model: AUDI Q4, SPORTBACK 45 E-TRON (A) Engine No: HIDDEN

Reg. Date: 22/08/2024 (Man. Year: 2024) Chassis No: WAUZZZFZ5RP074829

Colour: Blue Odometer: 3309 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19

Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,108.00	2,419.84	4,688.16	65.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,772.00	2,872.00	1,900.00	39.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,880.00	5,291.84	6,588.16	55.46
+ GST 9.00/9.00% (S\$)	1,069.20	476.27	592.93	55.46
Nett Amount (S\$)	12,949.20	5,768.11	7,181.09	55.46
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		6,090.29		

INSPECTION

Date of Assignment: 08/11/2024

Date Inspected: 08/11/2024 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Repair	1,178.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS UPPER	Not Necessary	204.00 FS	*- FS
3	1		*REAR BUMPER LOWER	Cut	956.00 FS	*764.40 FS
4	1		*REAR BUMPER SPOILER -SELENITE SILVER	Cut	307.00 FS	*245.60 FS
5	2		*REAR BUMPER DAMPING	Not Necessary	53.00 FS	*- FS
6	4		*REAR BUMPER SECURING STRIP	Necessary	106.00 FS	*84.80 FS
7	2		*REAR BUMPER SECURING STRIP	Necessary	53.00 FS	*42.40 FS
8	1		*REAR BUMPER TRIM	Cut	264.00 FS	*210.80 FS
9	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	98.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR -INNER	Not Necessary	572.00 FS	*- FS
11	4		*REAR PARKING AID SENSOR SEAL RING -INNER	Necessary	57.00 FS	*45.44 FS
12	1		*REAR REINFORCEMENT BEAM	Not Necessary	1,248.00 FS	*- FS
13	2		*REAR BUMPER GUIDE PROFILE-LH/RH	Not Necessary	132.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION -CENTER	Not Necessary	96.00 FS	*- FS
15	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	1,284.00 FS	*1,026.40 FS
16	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	7,108.00	2,419.84
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,600.00	600.00
3	TO RESPRAY REAR BUMPER ,REAR BUMPER MID AND BOTH REAR WHEEL ARCH TRIMS	New	2,600.00	1,700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			4,772.00	2,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >