

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0840/2024/KS
DATE : 6-Nov-24
WIP : 37334

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2024

YOUR INSURED VEH NO : SJB 5786 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR FOON WENG FOONG
ADDRESS : 167 STIRLING ROAD
#11-1209
SINGAPORE 140167
TELEPHONE : HP +65 93211332
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7240142438
VEHICLE NO : **SNS 8789 P**
MODEL CODE : AUDI Q4 SPORTBACK 45 E-TRON
MODEL YEAR : 22/8/2024
ENGINE NO : EDFA
CHASSIS NO : WAUZZZFZ5RP074829
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Nov-24
PLACE OF ACCIDENT : NEAR 18 TEBAN GARDENS CRES, SINGAPORE 608925
AYE, NEAR TEBAN GARDENS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNS 8789 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	280.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	
3	TO RESPRAY REAR BUMPER, REAR BUMPER MID AND BOTH REAR WHEEL ARCH TRIMS.	\$	2,600.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 4,772.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNS 8789 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 1,178.00	
2	REAR BUMPER FIXING PARTS - UPPER	1	\$ 204.00	
3	REAR BUMPER - LOWER	1	\$ 956.00	
4	REAR BUMPER SPOILER - SELENITE SILVER	1	\$ 307.00	
5	REAR BUMPER DAMPING	2	\$ 53.00	
6	REAR BUMPER SECURING STRIP	4	\$ 106.00	
7	REAR BUMPER SECURING STRIP	2	\$ 53.00	
8	REAR BUMPER TRIM	1	\$ 264.00	
9	REAR LIGHT REFLECTOR- LH / RH	2	\$ 98.00	
10	REAR PARKING AID SENSOR - INNER	2	\$ 572.00	
11	REAR PARKING AID SENSOR SEAL RING - INNER	4	\$ 57.00	
12	REAR REINFORCEMENT BEAM	1	\$ 1,248.00	
13	REAR BUMPER GUIDE PROFILE - LH / RH	2	\$ 132.00	
14	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 96.00	
15	REAR WHEEL ARCH COVER - LH / RH	2	\$ 1,284.00	
16	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 7,108.00	
TOTAL LABOUR CHARGES		:	\$ 4,772.00	
GRAND TOTAL		:	\$ 11,880.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT