



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SME3196T
Chassis No : MRHFC5650JT001464
Model : CIVIC 1.6 VTI YM2018
Owner's Name : NG YEEN PENG
Ins Policy No. :
Date of Accident :

Document No. : SQT24002956 **Page** 1
Date : 2. Nov 2024
Customer No. : WZF002
Svc Advisor : MARSLER
Engine No : R16B25501697
Date | Time : 2. Nov 2024 2:13:10 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NG YEEN PENG OWNER INSURER: INCOME ACC DATE: 02/11/2024 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SHB5123R						
71121-TEA-T02	BASE,FR.GRILLE CHROME <i>cu</i>	1	88.20 <i>145.50</i>	25 ✓	66.90	6.02	72.92
71125-TEA-T01	MOLDINGFR.GRILLE <i>one</i>	1	121.40 ✓	25 ✓	91.05	8.19	99.24
75700-TBA-A00	EMBLEM <i>11</i>	1	18.20 <i>11</i>	25 X	13.65	1.23	14.88
90301-ST0-003	NUT,PUSH 3MM <i>11</i>	2	2.10 <i>11</i>	25 X	3.15	0.28	3.43
71101-TEA-T00ZZ	FACEFR.BUMPER <i>11</i>	1	579.90 ✓	25 ✓	434.92	39.14	474.06
71102-TBA-A10	GRILLEFR.BUMPER LOWER <i>11</i>	1	43.80 X	25 X	32.85	2.96	35.81
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE <i>11</i>	1	21.80 X	25 X	16.35	1.47	17.82
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE <i>11</i>	1	21.80 X	25 X	16.35	1.47	17.82
71193-TEA-T01	SPACERR.FR.BUMPER SIDE <i>11</i>	1	10.40 X	25 X	7.80	0.70	8.50
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>11</i>	1	10.40 X	25 X	7.80	0.70	8.50
91505-TM8-003	CLIP,BUMPER <i>11</i>	20	2.30 ✓	25 ✓	34.50 ✓	3.11	37.61
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP <i>11</i>	1	260.00 X	25 X	195.00	17.55	212.55
71130-TEA-T00	BEAM COMPFR.BUMPER <i>11</i>	1	418.60 X	25 X	313.95	28.26	342.21
80525-TBA-A01	SENSOR ASSY,AMBIENT <i>11</i>	1	138.20 X	25 X	103.65	9.33	112.98
91555-TBA-K01	CLIPAMBIENT SENSOR <i>11</i>	1	5.90 X	25 X	4.42	0.40	4.82
80100-TBA-A02	CONDENSER ASSY <i>11</i>	1	704.40 X	25 X	528.30	47.55	575.85
33100-TEC-Q01	HEADLIGHT ASSY,R. <i>11</i>	1	708.80 X	25 X	531.60	47.84	579.44
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>11</i>	1	45.00 ✓	✓	45.00	4.05	49.05
Sum Item					2447.24	220.25	2,667.49

Printed on 4/11/2024 8:56:48 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SME3196T
Chassis No : MRHFC5650JT001464
Model : CIVIC 1.6 VTI YM2018
Owner's Name : NG YEEN PENG
Ins Policy No :
Date of Accident :

Document No. : SQT24002956
Date : 2. Nov 2024
Customer No. : WZF002
Svc Advisor : MARSLER
Engine No : R16B25501697
Date | Time : 2. Nov 2024 2:13:10 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00		100.00	9.00	109.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	200.00		200.00	18.00	218.00
BC012R	PERFORM DIAGNOSTIC / SCANNING	1	450.00		450.00	40.50	490.50
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	450.00		450.00	40.50	490.50
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1950.00		1950.00	175.50	2125.50
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1560.00		1560.00	140.40	1700.40
Sum Labor					4710.00	423.90	5,133.90

Survey By : Marcus Not Approved
Date & Time : 12/11/24 @ 9.30am.
Excess : When the body repair.
Status : 3 days
Signature : P/R H 206459

Total Amount 7,157.24 644.15 7,801.39
Total (Inclusive of GST) 7,801.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 4/11/2024 8:56:48 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.