

Not Withheld
11 Sep 2024

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7539L

AAD2410-099

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 OCT 2024

SHB7539L

JTDKB3FU503082658

200303878K

TOYOTA

PRIUS

26/10/24

GBH 3190Z / China

16/8/2019

		PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,641.36	✓	
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	243.81	✗	
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	493.40	✓	
1	WEATHERSTRIP, FRONT DOOR, LH	\$	292.32	X	
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	139.86	X	
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	123.06	X	
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	16.91	—	
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	55.02	—	
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	33.29	—	
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	1,161.83	X	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	300.62	X	
1	PILLAR, CENTER BODY, OUTER LH	\$	407.51	X	
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,634.33	✓	
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	243.81	X	
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	123.06	X	
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	369.60	X	
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	109.62	X	
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	124.74	X	
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	27.62	✓	
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	44.00	—	
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	19.43	—	
1	PANEL SUB-ASSY, QUARTER, LH	\$	1,099.46	X	
1	LINER, REAR WHEEL HOUSE, LH	\$	176.09	X	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2410-

SHB7539L

- 1 COVER, REAR BUMPER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

<i>n</i>	\$	<i>Per</i>	558.39	<i>X</i>
	\$	<i>Per</i>	111.41	<i>X</i>
	\$	<i>Per</i>	155.72	<i>X</i>
	\$	<i>Per</i>	1,695.65	<i>X</i>
	\$	<i>n</i>	624.54	<i>X</i>
TOTAL			\$ 12,026.43	
25%			\$ 3,006.61	
			\$ 9,019.82	

Special Nett

- 2SET DOOR TRIM CLIP
- 2SET DOOR WEATHERSTRIP CLIP
- 1 DOOR STICKER TRANSCAB
- 1 DOOR STICKER TEL NO.
- 1 FENDER LINER CLIP
- 1 REAR BUMPER CLIP
- 1SET CLIP, ROCKER PANEL MOULDING

\$	<i>nn</i>	130.00	<i>X</i>
\$	<i>nn</i>	130.00	<i>X</i>
\$	<i>nn</i>	100.00	<i>60sm</i>
\$	<i>nn</i>	100.00	<i>60sm</i>
\$	<i>nn</i>	65.00	<i>X</i>
\$	<i>nn</i>	65.00	<i>X</i>
\$	<i>nn</i>	65.00	<i>X</i>
TOTAL			\$ 655.00

TOTAL PARTS \$ 2,300.00**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>60d</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>60d</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>500d</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>1000d</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2410-**SHB7539L**

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL** \$ **4,550.00****Over All Total** \$ **15,869.82****(PART-BY-PART) Repair Days****12 Days***4 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: