

ASS. REC. BY:

REF:

C721 24110088 / Kmo3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7539L

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.G

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

593354

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU503082858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

Goodride 195/65R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

26/10/24

D.O.I.

29/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ

30/10 / 1 Pm @ 3800/- Car

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fines

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Not Whorish
11/24 83800h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7539L

AAD2410-099

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 OCT 2024

SHB7539L

JTDKB3FU503082658

200303878K

TOYOTA

PRIUS

26/10/24

GBH 3/902 /China

16/8/2019

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,641.36 ✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	243.81 ✗
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	493.40 ✓
1	WEATHERSTRIP, FRONT DOOR, LH	\$	292.32 ✗
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	139.86 ✗
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	123.06 ✗
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	16.91 —
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	55.02 —
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	33.29 —
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	1,161.83 ✗
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	300.62 ✗
1	PILLAR, CENTER BODY, OUTER LH	\$	407.51 ✗
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,634.33 ✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	243.81 ✗
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	123.06 ✗
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	369.60 ✗
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	109.62 ✗
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	124.74 ✗
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	27.62 ✓
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	44.00 —
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	19.43 —
1	PANEL SUB-ASSY, QUARTER, LH	\$	1,099.46 ✗
1	LINER, REAR WHEEL HOUSE, LH	\$	176.09 ✗

Trans-cab Auto Services Pte Ltd**AAD2410-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7539L

- 1 COVER, REAR BUMPER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

<i>n</i>	\$	<i>ScR</i>	558.39	<i>X</i>
	\$	<i>Sn</i>	111.41	<i>X</i>
	\$	<i>Sn</i>	155.72	<i>X</i>
	\$	<i>Sn</i>	1,695.65	<i>X</i>
	\$	<i>n</i>	624.54	<i>X</i>
TOTAL			\$ 12,026.43	
25%			\$ 3,006.61	
			\$ 9,019.82	

Special Nett

- 2SET DOOR TRIM CLIP
- 2SET DOOR WEATHERSTRIP CLIP
- 1 DOOR STICKER TRANSCAB
- 1 DOOR STICKER TEL NO.
- 1 FENDER LINER CLIP
- 1 REAR BUMPER CLIP
- 1SET CLIP, ROCKER PANEL MOULDING

	\$	<i>nn</i>	130.00	<i>X</i>
	\$	<i>nn</i>	130.00	<i>X</i>
	\$	<i>nn</i>	100.00	<i>60sm</i>
	\$	<i>nn</i>	100.00	<i>60sm</i>
	\$	<i>nn</i>	65.00	<i>X</i>
	\$	<i>nn</i>	65.00	<i>X</i>
	\$	<i>nn</i>	65.00	<i>X</i>
TOTAL			\$ 655.00	

TOTAL PARTS \$ 2,300.00**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>60l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>60l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>500l</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>1000l</i>

Trans-cab Auto Services Pte Ltd**AAD2410-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7539L

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL** \$ **4,550.00****Over All Total** \$ **15,869.82****(PART-BY-PART) Repair Days****12 Days***4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHB7539L

Vehicle to be Exported:

Yes

Intended Deregistration Date:

28 Oct 2024

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2ZR2C42885

Chassis No.:

JTDKB3FU503082658

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

16 Aug 2019

First Registration Date:

16 Aug 2019

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Aug 2027

PARF Rebate Amount:

\$9,972.00

Intended COE Rebate Details

COE Expiry Date:

15 Aug 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$23,463.00

COE Rebate Amount:

\$8,207.00

Total Rebate Amount:

\$18,179.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Oct 2024

OK