

Not Authorized
 LISB \$ 2300

Trans-cab Auto Services Pte Ltd

AAD2410-096

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7547M

Vehicle No.:
 Chassis No.:
 Co UEN:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

29 OCT 2024

SHB7547M

JTDKB3FU803081066
 200303878K
 TOYOTA
 PRIUS
 24/10/24
 GRK53938 / China
 31/5/2019

PART

LIST

1 COVER, REAR BUMPER	\$	Bu	558.39	✓
1 COVER, REAR BUMPER, LOWER	\$	Sn	19.43	X
1 GUARD, REAR BUMPER, CENTER	\$	CM	726.92	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R	419.90	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$	mjcm	155.72	✓
1 PANEL SUB-ASSY, QUARTER, LH	\$	R	1,099.46	} X
1 LINER, REAR WHEEL HOUSE, LH	\$	Sn	176.09	
1 COVER, FLOOR UNDER, NO.1 LH	\$	Sn	220.50	
1 COVER, REAR FLOOR	\$	Sn	290.43	
1 COVER, REAR COMBINATION LAMP, LH	\$	Sn	81.48	
1 LENS AND BODY, REAR LAMP, LH	\$	Sn	634.73	
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$	Sn	559.13	
1 SEAL, REAR SPOILER	\$	Sn	21.32	
1 SPOILER SUB-ASSY, REAR	\$	Sn	1,986.92	
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	R	824.46	
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	mjcm	1,171.38	✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	Me	68.88	✓
1 PLATE, BACK DOOR NAME, NO.1	\$	Me	68.88	✓
1 ORNAMENT SUB-ASSY, BACK DOOR	\$	Me	90.30	✓
TOTAL	\$		9,174.28	
25%	\$		2,293.57	
	\$		6,880.71	

Special Nett

1 REAR BUMPER CLIP \$ Me 65.00 Gosai

Trans-cab Auto Services Pte Ltd

AAD2410-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7547M

1 BOOT STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>30SN</i>
1 BOOT STICKER TEL NO	\$	<i>na</i>	100.00	<i>30SN</i>
1 FENDER LINER CLIP	\$	<i>na</i>	65.00	X
1 REAR TAIL LAMP CLIP	\$	<i>na</i>	65.00	X
TOTAL	\$		395.00	
<hr/>				
TOTAL PARTS	\$		8,543.40	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	<i>44d</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>15L</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	<i>20d</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
TOTAL	\$		5,990.00	
<hr/>				
Over All Total	\$		21,414.11	

(PART-BY-PART) Repair Days

.06 Days

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary terms and conditions is subject to final approval from Insurance Company

Acknowledged by Repairer: