

Not Authored  
L/Sy \$ 2300

AAD2410-096

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7547M**

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

29 OCT 2024

**SHB7547M**

JTDKB3FU803081066

200303878K

TOYOTA

PRIUS

24/10/24

GRK53938 / China

31/5/2019

	<b>PART</b>
1	COVER, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	FILLER, REAR BUMPER EXTENSION, LH
1	PANEL SUB-ASSY, QUARTER, LH
1	LINER, REAR WHEEL HOUSE, LH
1	COVER, FLOOR UNDER, NO.1 LH
1	COVER, REAR FLOOR
1	COVER, REAR COMBINATION LAMP, LH
1	LENS AND BODY, REAR LAMP, LH
1	LENS & BODY, REAR COMBINATION LAMP, LH
1	SEAL, REAR SPOILER
1	SPOILER SUB-ASSY, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR

	<b>LIST</b>
\$	Bu 558.39 ✓
\$	Su 19.43 X
\$	CM 726.92 ✓
\$	R 419.90 X
\$	ngcm 155.72 ✓
\$	R 1,099.46
\$	Su 176.09
\$	Su 220.50
\$	Su 290.43
\$	Su 81.48
\$	Su 634.73
\$	Su 559.13
\$	Su 21.32
\$	Su 1,986.92
\$	R 824.46
\$	ngcm 1,171.38 ✓
\$	su 68.88 —
\$	su 68.88 —
\$	su 90.30 ✓

**TOTAL \$ 9,174.28**  
**25% \$ 2,293.57**  
**\$ 6,880.71**

**Special Nett**

1 REAR BUMPER CLIP

\$ su 65.00 Gosai

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**AAD2410-**

**SHB7547M**

- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 FENDER LINER CLIP
- 1 REAR TAIL LAMP CLIP

\$	<i>na</i>	100.00	<i>30sn</i>
\$	<i>na</i>	100.00	<i>30sn</i>
\$	<i>na</i>	65.00	X
\$	<i>na</i>	65.00	X

**TOTAL \$ 395.00**

**TOTAL PARTS \$ 8,543.40**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>4401</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>15L</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2001</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

**TOTAL \$ 5,990.00**

**Over All Total \$ 21,414.11**

**(PART-BY-PART) Repair Days**

*06 Days*

*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "With-out Pre-judicial" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer and Company

Acknowledged by Repairer:  
Signature:  
Date: