

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07097

Vehicle Insured : SLQ8040A
Accident Date : 21-Jun-2024

Date : 22-Jun-2024

Our Ref : 024117 (CHINA) / CHAN

PAGE : 1

GABRIEL LEE HOCK HENG
BLK 341 WOODLANDS AVE 1
#07-613
Singapore 730341

*NOT Authorized
1/1/2024 \$4400/-
Refusing After Painting 6 days*

ESTIMATED COST OF REPAIR FOR TOYOTA WISH SLL1096L

1 pc Tail gate
1 pc Tail gate logo
1 pc Tail gate glass moulding
1 pc Tail gate rubber
1 pc Tail gate inner lock
1 pc Rear end panel -inner
1 pc Rear end panel -outer
1 pc End panel top garnish
1 pc Rear bumper fascia
2 pcs Rear bumper side retainer-L
2 pcs Rear bumper side retainer-S
2 pcs Rear bumper bracket
2 pcs Rear bumper reflector

PM	1,599.30	✓
RM	57.70	—
RM	155.80	—
RM/MI	363.60	50% 181.80
RM	446.30	—
RM	119.90	—
RM	580.80	—
RM	322.70	—
RM/UM	639.70	—
MI	211.00	—
MI	99.40	—
R	116.60	X
R	130.00	X
4,842.80		
Less 25% :	1,210.70	

1 pc Rear bumper reverse sensor(set)
1 pc Rear w/s glass sealant
1 pc Rear bumper clip
1 pc Rear no.plate with box

GR 2000 3,632.10
RM 300.00 sn 400
RM 60.00 sn 400
RM 30.00 sn 400
RM 50.00 sn 450

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 1200

To remove roof lining, front and
rear seats, trim board and carpet

150.00 600

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ8040A

Page : 2

To apply undersealing

60.00 ✓

To putty and spray replaced parts

1,000.00 *Boel*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 *Boel*

Total : S\$ 6,332.10

=====

Singapore Dollars Six Thousand Three Hundred
and Thirty Two and Cents Ten Only