

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07097

Vehicle Insured : SLQ8040A
Accident Date : 21-Jun-2024

Date : 22-Jun-2024

Our Ref : 024117 (CHINA) / CHAN

PAGE : 1

GABRIEL LEE HOCK HENG
BLK 341 WOODLANDS AVE 1
#07-613
Singapore 730341

NOT Authorized
11 Sep 8
Anthony After Rain

ESTIMATED COST OF REPAIR FOR TOYOTA WISH SLL1096L

1 pc Tail gate		Pr 1,599.30	✓
1 pc Tail gate logo		Pr 57.70	—
1 pc Tail gate glass moulding		Pr 155.80	—
1 pc Tail gate rubber		Pr 363.60	50% in
1 pc Tail gate inner lock		Pr 446.30	—
1 pc Rear end panel -inner		Pr 119.90	—
1 pc Rear end panel -outer		Pr 580.80	—
1 pc End panel top garnish		Pr 322.70	—
1 pc Rear bumper fascia		Pr 639.70	—
2 pcs Rear bumper side retainer-L	@ S\$105.50	Pr 211.00	—
2 pcs Rear bumper side retainer-S	@ S\$ 49.70	Pr 99.40	—
2 pcs Rear bumper bracket	@ S\$ 58.30	116.60	?
2 pcs Rear bumper reflector	@ S\$ 65.00	Pr 130.00	X

4,842.80

Less 25% : 1,210.70

- 1 pc Rear bumper reverse sensor(set)
- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper clip
- 1 pc Rear no.plate with box

Gr 2008N 3,632.10
Pr 300.00 sn 40% in
Pr 60.00 sn 40% in
Pr 30.00 sn
Pr 50.00 sn 45% in

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 120%

To remove roof lining, front and
rear seats, trim board and carpet

150.00 60%

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ8040A

Page : 2

To apply undersealing

60.00 ✓

To putty and spray replaced parts

1,000.00 *Feel*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 *Feel*

Total : S\$ 6,332.10
=====

Singapore Dollars Six Thousand Three Hundred
and Thirty Two and Cents Ten Only