

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP / RES / OD RES / EVA / INV / MV
 To In: _____
 at V/O: _____
 of _____
 Insured: _____
 Policy No: _____
 Claim's No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of V/O: _____
 (Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKWS8326 Yr Regn: 2015, Nov
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel C.D. 1496
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 127851 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Ru11106028
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 25/10/24
 Survey held at JL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Claim</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 20K</u>
	<u>PV: 11.5K</u>
	<u>Nett: 8.5K</u>
	<u>NOTE</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)

Survey Fee: _____

Transportation: _____

B + R. \$1

Photos

Others

Report Formist: _____

Report Formist: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 25.10.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SKW5832G
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 25.10.2024
TIME OF ACCIDENT : 11:40 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Del'd</i>	1	\$ 865.50	\$ 865.50
2	REAR BUMPER SIDE <i>Del'd LH</i>	2	\$ 195.00	\$ 390.00
3	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 49.30	\$ 98.60
4	REAR BUMPER REFLECTOR LH <i>Curbed</i>	1	\$ 151.10	\$ 151.10
5	TAILGATE <i>Repair</i>	1	\$ 1,100.00	\$ 1,100.00
6	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 220.00	\$ 220.00
7	TAILGATE SIDE LAMP LH <i>new</i>	1	\$ 240.00	\$ 240.00
8	TAILGATE EMBLEM 'VEZEL' <i>new</i>	1	\$ 48.00	\$ 48.00
9	TAILGATE TOP LOCK <i>new</i>	1	\$ 175.00	\$ 175.00
10	TAILGATE LOWER LOCK <i>new</i>	1	\$ 24.70	\$ 24.70
11	TAILGATE INNER TRIM <i>new</i>	1	\$ 398.60	\$ 398.60
12	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 168.40	\$ 168.40
13	TAILGATE WINDSCREEN MOULDING (SET) <i>new</i>	1	\$ 164.00	\$ 164.00
14	BUZZER <i>new</i>	1	\$ 80.00	\$ 80.00
15	TAIL LAMP <i>Curbed LH</i>	2	\$ 475.00	\$ 950.00
16	TAIL LAMP PANEL LH <i>Repair</i>	1	\$ 327.60	\$ 327.60
17	TAIL LAMP INNER PANEL LH <i>new</i>	1	\$ 389.70	\$ 389.70
18	REAR FENDER LH <i>Curbed</i>	1	\$ 926.40	\$ 926.40
19	REAR FENDER INNER PANEL LH <i>Repair</i>	1	\$ 853.00	\$ 853.00
20	REAR FENDER INNER TRIM <i>Del'd</i>	2	\$ 298.60	\$ 597.20
21	REAR FENDER AIR VENT LH <i>Del'd</i>	1	\$ 74.30	\$ 74.30

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKW5832G
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 25.10.2024
 TIME OF ACCIDENT : 11:40 HOURS

22	REAR FENDER COWLING LH <i>Completed LH</i>	2	\$ 150.20	\$ 300.40	<i>150.20</i>
23	REAR FENDER ARCED GARNISH LH <i>LH Deland</i>	2	\$ 184.70	\$ 369.40	<i>184.70</i>
24	REAR WHEEL HOUSE PANEL LH <i>34</i>	1	\$ 896.30	\$ 896.30	<i>+</i>
25	REAR WHEEL HOUSE UPPER PANEL LH <i>74</i>	1	\$ 653.20	\$ 653.20	<i>+</i>
26	REAR WHEEL RIM RH <i>cut</i>	1	\$ 1,450.00	\$ 1,450.00	<i>450.00 (sw)</i>
27	REAR AXLE <i>new</i>	1	\$ 1,670.00	\$ 1,670.00	<i>+</i>
28	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 398.00	\$ 398.00	<i>+</i>
29	REAR WHEEL HUP COME WITH BEARING RH <i>new</i>	1	\$ 435.00	\$ 435.00	<i>+</i>
30	REAR WHEEL SPEED SENSOR RH <i>new</i>	1	\$ 285.00	\$ 285.00	<i>+</i>
31	REAR DOOR LH <i>2</i>	1	\$ 1,427.30	\$ 1,427.30	<i>+</i>
32	REAR DOOR INNER TRIM BOARD LH <i>del</i>	1	\$ 1,120.60	\$ 1,120.60	<i>+</i>
33	REAR DOOR INNER LOCK LH <i>del</i>	1	\$ 385.40	\$ 385.40	<i>+</i>
34	REAR DOOR WEATHER STRIP LH <i>del</i>	1	\$ 196.70	\$ 196.70	<i>+</i>
35	REAR END PANEL <i>new</i>	1	\$ 530.00	\$ 530.00	<i>+</i>
36	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 146.30	\$ 146.30	<i>✓</i>
37	REAR FLOOR SIDE PANEL LH <i>Disland</i>	1	\$ 297.60	\$ 297.60	<i>✓</i>
38	REAR FLOOR PANEL BOTTOM GARNISH <i>del</i>	1	\$ 269.00	\$ 269.00	<i>✓</i>
39	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 300.40	\$ 300.40	<i>+</i>
40	REAR TOOLS SPONGE <i>new</i>	1	\$ 215.30	\$ 215.30	<i>+</i>
41	REAR CHASSIS MEMBER LH <i>new</i>	1	\$ 797.40	\$ 797.40	<i>+</i>

TOTAL PRICE \$ 20,385.40
 LESS 20% \$ 4,077.08
SUB TOTAL PRICE \$ 16,308.32

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS					
S/N	DESCRIPTION		QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>		1	\$ 50.00	\$ 50.00
2	TAIL LAMP CLIP (SET) <i>new</i>		1	\$ 30.00	\$ 30.00
3	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>		1	\$ 30.00	\$ 30.00
4	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>		1	\$ 50.00	\$ 50.00
5	TAILGATE WINDSCREEN SEALANT <i>new</i>		1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN INNER SEAL <i>new</i>		1	\$ 60.00	\$ 60.00
7	REAR FENDER SEALANT RH <i>new</i>		1	\$ 80.00	\$ 80.00
8	REAR FENDER INNER TRIM CLIP (SET)	<i>new</i>	1	\$ 60.00	\$ 60.00

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKW5832G**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 25.10.2024
 TIME OF ACCIDENT : 11:40 HOURS

9	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+ 20</i>
10	REAR FENDER ARCED GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+ 20</i>
11	REAR QUARTER GARNISH SEALANT RH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+ 10</i>
12	REAR QUARTER GARNISH INNER SHIELD RH <i>new</i>	1	\$ 40.00	\$ 40.00	<i>+ 10</i>
13	REAR DOOR INNER TRIM BOARD CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+ 10</i>
14	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+ 10</i>
15	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	<i>+ 10</i>
16	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+ 10</i>
17	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	<i>+ 10</i>

TOTAL \$ 1,400.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>1000</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>X</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	<i>X</i>
8	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>X</i>
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>X</i>
10	TRANFER TAILGATE MECHANISM	\$ 80.00	<i>X</i>
11	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>X</i>

TO : CHINA TAIHING MOTOR CLAIMS DEPTS
VEHICLE NO : SKW5832G
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 25.10.2024
TIME OF ACCIDENT : 11:40 HOURS

12	TRANFER REAR DOOR MECHANISM	\$ 80.00	X
13	REMOVE AND REFIX REAR QUARTER GARNISH	\$ 100.00	40
14	REMOVE AND REFIX FUEL TANK TO FACILITE FLOOR PANEL REPLACEMENT	\$ 80.00	X
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,730.00

TOTAL PARTS COST : \$ 17,708.32
TOTAL LABOUR COST : \$ 5,730.00
TOTAL REPAIR COST : \$ 23,438.32

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/s 25/10/24.

09 Days