

ASS. REC. BY:

REF: C72/

CS

CT124110098/Knp3

C

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 873k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 1.0B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: Smd 17526Yr Regn: 08.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mit OutlanderC.C. 1998Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 62944

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GFW 0401993Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 15/9/24D.O.I. 7/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12 81676-50 Combi (Red, \$579.30, 25%)

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 369J

Vehicle Details

Vehicle No.: SMD1752G
Vehicle to be Exported: No
Intended Deregistration Date: 20 Sep 2024
Vehicle Make: MITSUBISHI
Vehicle Model: OUTLANDER 2.0 CVT SUNROOF
Primary Colour: White
Manufacturing Year: 2018
Engine No.: 4J11YP5405
Chassis No.: GF7W0401993
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$22,179.00
Original Registration Date: 06 Aug 2018
First Registration Date: 06 Aug 2018
Transfer Count: 0

Actual ARF Paid: \$23,051.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Aug 2028
PARF Rebate Amount: \$14,983.00

Intended COE Rebate Details

COE Expiry Date: 05 Aug 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$31,000.00
COE Rebate Amount: \$12,016.00
Total Rebate Amount: \$26,999.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 20 Sep 2024

OK



Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMD 1752G

TP/china

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62221033

ATTN: Motor Claim Department

Claim No: ES2400921

Estimate No: ES2400921/YISHUN

Date: 06 Nov 2024

Policy No: 5147067404

Veh Reg No: SMD1752G

Make/Model: MITSUBISHI MIT.
OUTLANDER 2.0 CVT
SUNROOF

Chassis No: GF7W0401993

Engine No: 4J11YP5405

Reg. Date: 06/08/2018

WS Ref: TP/CHINA

Claim Type: Third Party

Accident Date: 15/09/2024

TP Veh Reg No: SLR1891B

Not Authorized

Recovery Bypass

3 days

@ 1670.50

Estimate Repair Cost to Vehicle No : SMD1752G

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR BUMPER	520.00	1 PC	520.00	✓
2 REAR BUMPER CENTRE LOWER SKIRT	135.00	1 PC	135.00	✓
3 REAR SMART KEY SENSOR	50.00	1 PC	50.00	R
4 TAILGATE EMBLEM (OUTLANDER)	58.00	1 PC	58.00	+
5 TAILGATE EMBLEM (MIVEC)	55.00	1 PC	55.00	+
			818.00	
	Add 10%		81.80	899.80
Special Net				
6 REAR REVERSE SENSOR	200.00	1 SET	200.00	✓
				200.00
Labour				
7 REMOVE & REFIX REAR BUMPER ASSY,KNOCK & REPAIR REAR END PANEL,TAILGATE AND REALIGN THE SAME	500.00	1 LA	500.00	300
8 PUTTY & RESPRAY ON REAR BUMPER,LOWER SKIRT,TAILGATE,REAR PANEL	600.00	1 LA	600.00	400
9 REMOVE & REFIX REVERSE CAMERA,SMART KEY SENSOR,SMART KEY SENSOR AND RESET SYSTEM	50.00	1 LA	50.00	✓
				1,150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged: Repairer
Signature:
Date:

Total	S\$ 2,249.80
Add GST @ 9%	202.48
Total Amount payable	S\$ 2,452.28

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE