



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24060254/Avh3
75 BRAS BASAH ROAD	Date:	23/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 2163T	Veh. Inspected	SKW 6800S
Policy No.	-	Coverage	0
Claim No.	MT/1283275-002	Excess	\$0.00
Assign From	ENG HUEY HUEY	Assign Date	26/06/2024

2. Vehicle Details

Make & Model	TOYOTA LEXUS GS250	C.C	2500
Engine No.	4GR1068233	Year of Reg.	23/10/2015
Chassis No.	JTHBF5BL60A001187	Colour	WHITE
Odometer	338115 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40R18	PIRELLI	6
L/H Front Tyre	245/40R18	PIRELLI	6
R/H Rear Tyre	245/40R18	PIRELLI	6
L/H Rear Tyre	245/40R18	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/06/2024	Inspection Date	26/06/2024 (10:36)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days