

KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD. UEN: 201502816H
68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896
Tel: (+65) 6384 1956 Fax: (+65) 6384 1957
Webpage: <https://www.kaizenmotors.com.sg>

 kaizenmotorsingapore

 kaizen_motors

 kaizenmotors

Date : 04/11/2024
Vehicle No : SKW5159S
Model : Subaru XV
Mileage :

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	REAR TAIL GATE ¹¹	1	\$ 1,567.00	\$ 1,567.00 X
2	REAR SUBARU EMBLEM ¹¹	1	\$ 106.00	\$ 106.00 X
3	REAR AWD EMBLEM ¹¹	1	\$ 106.00	\$ 106.00 X
4	REAR XV EMBLEM ¹¹	1	\$ 95.00	\$ 95.00 X
5	REAR BUMPER ^{De / Torn}	1	\$ 1,036.00	\$ 660 1,036.00
6	REAR BUMPER CHROME GARNISH ^{Dis}	1	\$ 513.50	\$ 513.50
7	REAR BUMPER TOW COVER ^{m.i}	1	\$ 66.00	\$ 38 66.00
8	REAR BUMPER FOG LAMP ^{See}	2	\$ 273.00	\$ 546.00 X
9	REAR BUMPER RETAINER ^{antenna sensor one}	2	\$ 109.00	\$ 180 218.00
10	REAR REINFORCEMENT BEAM ^{5mf}	1	\$ 575.00	\$ 227 309 575.00
11	REAR BUMPER CLIPS ^{all}	1 set 10	\$ 8.00	\$ 80.00 30 S/N
12	REVERSE SENSOR ^{modification}	1 set 2	\$ 150.00	\$ 300.00 200 S/N
13	LABOUR FOR CHECKING ON WIRING		\$ 250.00	\$ 250.00 20
14	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR END ASSY & PARTS		\$ 2,500.00	\$ 2,500.00 400
15	SPRAYPAINTING & PUTTY OF REAR BUMPER, REAR BOOT REAR DIFFUSER, REINFORCEMENT BEAM, FENDER		\$ 1,200.00	\$ 1,200.00 520
16	LABOUR FOR RETROFITTING MOULDING & SEAL		\$ 550.00	\$ 11 550.00 X
17	LABOUR FOR RUST PROOFING		\$ 350.00	\$ 11 350.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$ 10,058.50

Not Authorized
on
moras
18/11/24
1/5 # 2000
take photo after repair
3 days