

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TEL: 65096584

TO	: INDIA INTERNATIONAL	DATE	4/11/2024
VEHICLE NO	: SMG9307R (2019)		
VEHICLE MODEL	: TOYOTA NOAH HYBRID		Xiao Chen.
CHASSIS NO	: ZWR800347896		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 78.90	\$ 157.80
2	REAR BUMPER <i>distorted</i>	1	\$ 1,025.50	\$ 1,025.50
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 70.90	\$ 141.80
4	REAR BUMPER TOW COVER <i>new</i>	1	\$ 28.10	\$ 28.10
5	REAR BUMPER REFLECTOR <i>RH cracked</i>	2	\$ 85.90	\$ 171.80
6	REAR END PANEL <i>Dented</i>	1	\$ 735.70	\$ 735.70
7	REAR END PANEL TOP GARNISH <i>Deformed</i>	1	\$ 148.60	\$ 148.60
8	REAR END PANEL ANTENNA SENSOR <i>Cracked</i>	1	\$ 184.60	\$ 184.60
9	TAILLAMP <i>new</i>	2	\$ 685.10	\$ 1,370.20
10	TAILLAMP OUTER PANEL <i>Repair</i>	2	\$ 311.10	\$ 622.20
11	TAILLAMP LOWER APRON <i>Deformed</i>	2	\$ 178.80	\$ 357.60
12	TAILGATE <i>Distorted</i>	1	\$ 1,812.70	\$ 1,812.70
13	TAILGATE LOCK <i>Dented</i>	1	\$ 375.10	\$ 375.10
14	TAILGATE LOWER LOCK CATCH <i>new</i>	1	\$ 38.90	\$ 38.90
15	TAILGATE WEATHERSTRIPE <i>cut</i>	1	\$ 375.10	\$ 375.10
16	TAILGATE OUTER MOULDING <i>cracked</i>	1	\$ 581.50	\$ 581.50
17	TAILGATE INNER TRIM BOARD <i>cracked</i>	1	\$ 761.80	\$ 761.80
18	TAILGATE DAMPER <i>3HP</i>	2	\$ 326.80	\$ 653.60
19	TAILGATE HINGE <i>3HP</i>	2	\$ 113.40	\$ 226.80
20	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 185.20	\$ 185.20
21	TOYOTA LOGO <i>New</i>	1	\$ 78.20	\$ 78.20
22	HYBRID EMBLEM <i>New</i>	1	\$ 58.40	\$ 58.40
23	REAR FENDER INNER TRIM BOARD <i>Deformed</i>	2	\$ 906.50	\$ 1,813.00
24	REAR FENDER INNER SHIELD <i>new</i>	2	\$ 125.90	\$ 251.80
25	JACK COVER <i>new</i>	1	\$ 128.70	\$ 128.70
26	FLOOR PANEL <i>Repair</i>	1	\$ 980.80	\$ 980.80
27	FLOOR PANEL TOP BOARD <i>cracked</i>	1	\$ 1,105.50	\$ 1,105.50
28	FLOOR PANEL MAT <i>new</i>	1	\$ 582.40	\$ 582.40
29	REAR EXHAUST PIPE <i>3HP</i>	1	\$ 892.50	\$ 892.50
30	REAR EXHAUST PIPE MOUNTING <i>3HP</i>	1	\$ 38.90	\$ 38.90
31	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 35.20	\$ 35.20
32	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 188.20	\$ 188.20

TOTAL PRICE: \$ 16,108.20
LESS 25% \$ 4,027.05
SUB TOTAL PRICE: \$ 12,081.15

9393.90

7045.42

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>344</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>344</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
5	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	TAILLAMP LOWER APRON CLIPS <i>new</i>	2 SET	\$ 20.00	\$ 40.00
7	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
8	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
9	REAR CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00
10	REAR VIDEO CAMERA <i>new</i>	1	\$ 580.00	\$ 580.00
11	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00
12	REAR FENDR INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00
13	FLOOR PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00

TOTAL : \$ 1,510.00

Reverse Sensor

Dangled

280 200.

500

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>800</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>60</i>	
5	TO REMOVE REAR UPHOLSTERY & REAR LH & RH SEATS	\$ 380.00	<i>60</i>	
6	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	<i>x</i>	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>60</i>	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	<i>120</i>	
10	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>x</i>	

TOTAL: \$ 4,310.00

1980

ESTIMATE REPORT

TOTAL PARTS COST: \$ 13,591.15

TOTAL LABOUR COST: \$ 4,310.00

TOTAL REPAIR COST: \$ 17,901.15

total: 9525.42

L/S: 7.6K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: