ASS. REC. BY: Kenneth	CS/CTI24110107/Kvp3
TENNETH	ASSIGNMENT
From: Date:	Veh No: S2H 1879K Yr Regn: 10, 16
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Traller or
To Inspect Vehicle No:	1 - 11
at Workshop m/s Clank	Make: Itudi A6 c.c 1984
of	Colour M. Orange Kory A/C: Insured / Std / NI / NA
Insured: SMX 1068T	Sp.Reading 90069 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
the state of the s	CNO: WAUZZZZ4426N15342
Claims No. SNM24D206194C02	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
,	Tyre Size: F: 2.45/1.572.0
(Policy Condition)	047143 EKIJ
Remark: The veh had commenced its N/S O/	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA /MIC / OHTSU / PIR / SUM! / TOYO / YOKO or
Bal. or Market Value: & 47K	Fridamental 1-12 control - 1-12 cont
IDAC Accident Rport: Consistent? : Yes or No	Fron! Rear O
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 3 mm 'R/Bal. mm
Est. Repairs: 03 days Res.: Yes or No	L/Bal. 3 mm L/Bal.
Lum Sum: 1/B/ % 3 Val.: Yes or No	D.O.A. 31/10/26 D.O.I. 26/11/202
To ordin les of Mo	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OU	- Landau - L
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
The state of the s	
13/8	
21/8/25 Final fig \$2509.72 confirmed with J	Jenny (Red 20, 0%)
-	
	and the second s
nto/Time, File Pass to?	
: Prell. Report	Days Of Repair: 3
: Final Report	Resurvey No. of Trip: Survey Fee:
	Transportation
Add Fee:	: Site Insp (\$)_s - Rs_si
med Factors	Intension (\$
port Format :	Tech Inve (\$
) Others
mp Sum / I.B.I: (\$	I the same and the
mp Sum / I.B.I: (\$	Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 808Z

Vehicle Details

Vehicle No.: SLH1979K

Vehicle to be Exported: Yes

Intended Deregistration Date: 01 Nov 2024
Vehicle Make: AUDI

Vehicle Model: A6 2.0 TFSI (PI)

Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: CYP014397

Chassis No.: WAUZZZ4G2GN153420

Maximum Power Output: 185.0 kW (248 bhp)
Open Market Value: \$44,297.00

Original Registration Date: 26 Oct 2016
First Registration Date: 26 Oct 2016

Transfer Count: 1

Actual ARF Paid: \$54,016.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Oct 2026
PARF Rebate Amount: \$29,708.00

Intended COE Rebate Details

COE Expiry Date: 25 Oct 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

 QP Paid:
 \$55,501.00

 COE Rebate Amount:
 \$10,995.00

 Total Rebate Amount:
 \$40,703.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. The information contained herein is correct as at 01 Nov 2024

Lai Huat (Meng Kee) Motor Pte Ltd 160 Sin Ming Drive, #04-01, #04-02 & #07-03. Sin Ming Autocity

575722

Insurer Reference: TP-SMX1068T

Repairer Reference: 74807

Date calculated: 05/11/2024 3:17 PM

Full Report

Registration: SLH1979K Printed: 05/11/2024 3:17 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Jenny Lim TP-SMX1068T Currency: Date of Incident: Hire Car Start:

Hire Car End:

SGD 31/10/24

Vehicle Details

Vehicle

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration:

VIN number: Odometer:

Model Specs

FROM 06.2015 HEADLAMP WASHERS D/MIRR MEM/FOLD/DIP MMI RADIO HIGH/NAVIG

KEYLESS ENTRY DRIVER INFO COLOUR

HD COOLING

REAR BRAKE 330X22

AUDI CONNECT

EQUIP LEATHER MILANO

AUDI

A6 (4GC/4GD) BASE MODEL 00 81 01

SLH1979K

WAUZZZ4G2GN153420

88467

WHEELS 8J X 18 ALU **AUTO BOOTLID**

TOUCHPAD

ACTIVE LOUD SPEAKER SPLIT REAR SEAT LIGHT PACK 1984CCM 185KW SPORTS SUSPENSION

TWO COAT METALLIC

TRIM PARTS ALUMINIUM

EMISSION STD EURO 6 AIR CON AUTO 4-ZONES AUTO DIPPING MIRROR LED HEADLAMP

SPORT S-WHEEL LEATH FRONT CENTRE ARMREST ELEC/SEAT ADJ MEMORY

S-TRONIC

CRUISE CONTROL **ESP PROGRAMME**

Not Notherital Resury Bépassy 3day,

STOP-START SYSTEM REARVIEW CAMERA HIGH BEAM ASSISTANT ULTRASONIC PARK SYS **ELECT LUMBAR ADJUST** FRONT BRAKE 345 X 30 TYRES 245/45 R18..Y

SALOON

Labour

(200 maria de 6 mario depuis de Control de Propinsión de Austria de Control d	Time Base 10 WU/h	Price = 42.00 SGD/h
Code	Description	WU Price SGD
63 69 19 00	R + R REAR BUMPER COVER INCLUDES: BOTH OUTER TAILLAMPS REMOVE AND REFIT	9.0 37.80
63 69 55 55	RENEW REAR BUMPER COVER (BUMPER COVER REMOVED) INCLUDES:SENSORS AND REAR LOWER SPOILER R + R	3.0 12.60

Insurer Reference: TP-SMX1068T Repairer Reference: 74807

Date calculated: 05/11/2024 3:17 PM

Full Report Registration: SLH1979K

Printed: 05/11/2024 3:17 PM

50.40

Hrs WU **Labour Cost** Panel / Mechanical Labour 1.20 12.0

50.40 **Total of Labour**

Paint

Paint Work	SYSTEM AZT	Time Basis	10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD

REAR BUMPER NEW PART PAINT K1R 11.0

Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	54.12

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			11.0	
Preparation Comp. Work Plastic		0.90	9.0	37.80
Total	10 WU/h	2.00	20.0	84.00

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	54.12
Material-constant Plastic	16.20
Total	70.32

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-09-02/23 Price SGD
2581	REAR BUMPER	4G5 807 067 G	Original	Bu 1,300.00
2605	REAR BUMPER SPOILER	GRU 4G0 807 521 P 9B9	Original	DU/6-67 250.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Fixed Sundry Parts I Addition(+10.00%)	Price		0.00 1,550.00 100.00 155.00

Extras

Code	Description	Price SGD
1000 1001	CHK/ERASE FAULT CODE AFTER REPAIR WRAP FOR REAR BUMPER Total Extras	x 7 _{120.00*} (Bill)500-400.00* 520.00

Total

1,805.00

Insurer Reference: TP-SMX1068T

Repairer Reference: 74807

Date calculated: 05/11/2024 3:17 PM

Full Report Registration: SLH1979K

Printed: 05/11/2024 3:17 PM

Final Calculation

	SGD	SGD
Parts Fixed Sundry Parts Price	1,550.00 100.00	
Addition(+10.00%)	155.00	
Total Parts		1,805.00
Labour Time Base 10 WU/h		
Total 12.0 WU X 42.00 SGD/h	50.40	
Total of Labour		50.40
Total Of Extras		520.00
Paint Work Time Base 10 WU/h		
Labour Cost 20.0 WU X 42.00 SGD/h	84.00	
Material Cost Total Paint Including Material	70.32	154.32
Total Paint Including Material		137.32
Repair Cost Excludes GST		2,529.72
GST (+9.00%)		227.67
Repair Cost Included GST		2,757.39

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resun
- Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: