

ASS. REC. BY:

REF: C721Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s CLARK

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 847K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1.01 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 1979K Yr Regn: 10.16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or A1Make: Audi A6 c.g. 1984Colour: M. Orange AC: Insured / Std / NI / NASp. Reading: 90089 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WUAU888462GN153420Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Jm or

Tyre Size: F: 245/45ZR18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 3 mm R/Bal. 8 mmL/Bal. 3 mm L/Bal. 8 mmD.O.A. 31/10/24 D.O.I. 26/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS. \$

F. P. AS

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 & #07-03,
Sin Ming Autocity
575722

Insurer Reference: TP-SMX1068T
Repairer Reference: 74807
Date calculated: 05/11/2024 3:17 PM

Full Report
Registration: SLH1979K
Printed: 05/11/2024 3:17 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-SMX1068T	Date of Incident:	31/10/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	AUDI
Model:	A6 (4GC/4GD)
Sub Model:	BASE MODEL
Model Sheet Number:	00 81 01
Registration:	SLH1979K
VIN number:	WAUZZZ4G2GN153420
Odometer:	88467

Model Specs
FROM 06.2015
HEADLAMP WASHERS
D/MIRR MEM/FOLD/DIP
MMI RADIO HIGH/NAVIG
KEYLESS ENTRY
DRIVER INFO COLOUR
HD COOLING
REAR BRAKE 330X22
AUDI CONNECT
EQUIP LEATHER MILANO

WHEELS 8J X 18 ALU
AUTO BOOTLID
TOUCHPAD
ACTIVE LOUD SPEAKER
SPLIT REAR SEAT
LIGHT PACK
1984CCM 185KW
SPORTS SUSPENSION
TRIM PARTS ALUMINIUM
TWO COAT METALLIC

EMISSION STD EURO 6
AIR CON AUTO 4-ZONES
AUTO DIPPING MIRROR
LED HEADLAMP
SPORT S-WHEEL LEATH
FRONT CENTRE ARMREST
S-TRONIC
CRUISE CONTROL
ESP PROGRAMME

STOP-START SYSTEM
REARVIEW CAMERA
HIGH BEAM ASSISTANT
ULTRASONIC PARK SYS
ELECT LUMBAR ADJUST
ELEC/SEAT ADJ MEMORY
FRONT BRAKE 345 X 30
TYRES 245/45 R18..Y
SALOON

*Not Authored
Repairing 84 parts
3 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
63 69 19 00	R + R REAR BUMPER COVER INCLUDES: BOTH OUTER TAILLAMPS REMOVE AND REFIT		9.0	37.80
63 69 55 55	RENEW REAR BUMPER COVER (BUMPER COVER REMOVED) INCLUDES: SENSORS AND REAR LOWER SPOILER R + R		3.0	12.60

Insurer Reference: TP-SMX1068T
Repairer Reference: 74807
Date calculated: 05/11/2024 3:17 PM

Full Report
Registration: SLH1979K
Printed: 05/11/2024 3:17 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	1.20	12.0	50.40
Total of Labour			50.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	11.0

Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	54.12

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		11.0	
Preparation Comp. Work Plastic	0.90	9.0	37.80
Total	10 WU/h	2.00	20.0 84.00

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	54.12
Material-constant Plastic	16.20
Total	70.32

Spare Parts

				prices as at 2015-09-02/23
Code	Description	Part Number	Part Source	Price SGD
2581	REAR BUMPER	4G5 807 067 G GRU	Original	Ben 1,300.00 ✓
2605	REAR BUMPER SPOILER	4G0 807 521 P 9B9	Original	Dul/Ben 250.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,550.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Addition(+10.00%)			155.00
	Total			1,805.00

Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE AFTER REPAIR	7 120.00*
1001	WRAP FOR REAR BUMPER	(Bill) ✓ 400.00*
	Total Extras	520.00

Insurer Reference: TP-SMX1068T
Repairer Reference: 74807
Date calculated: 05/11/2024 3:17 PM

Full Report
Registration: SLH1979K
Printed: 05/11/2024 3:17 PM

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	1,550.00	
Addition(+10.00%)	100.00	
Total Parts	155.00	1,805.00
Labour Time Base 10 WU/h		
Total 12.0 WU X 42.00 SGD/h	50.40	
Total of Labour		50.40
Total Of Extras		520.00
Paint Work Time Base 10 WU/h		
Labour Cost 20.0 WU X 42.00 SGD/h	84.00	
Material Cost	70.32	
Total Paint Including Material		154.32
Repair Cost Excludes GST		2,529.72
GST (+9.00%)		227.67
Repair Cost Included GST		2,757.39

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	01/11/2024 16:08 (SGT)
Reported by	Actual Driver
Date of Accident	31/10/2024 11:55 (SGT)
Exact Location of Accident	Bayfront Ave, Singapore
Additional Location Information	towards Suntec City
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH1979K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Teh Dan Lin
NRIC No	SXXXX808Z
Email Address	kelvin.kwee@gmail.com
Mobile Phone No	(Phone) +65-96773173
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A6
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	-

DRIVER

Bayfield Avenue



Car 1: SHL 1079K

2: SKG 3282M

3: SMX 1068T

Marina Bay

2nd Tower 1