

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT124110109/Unh3e2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBG 3333J

at Workshop m/s Trans Eurofers 10a

of _____

Insured: G.Y. SOUTER

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value: \$ 78k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 7276

Date: _____ Person Contacted: LIA 26837

Vehicle: IN / OUT

Veh No: SBG 3333J Yr Regn: 15/08/19

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / M-Hybrid

Make: mazda 3 c.c. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 85757 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BP2SAAK 1100909

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/10/24 D.O.I. 11/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Prt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 207146.

9/12/24 remove PPF sticker labour for fender
PIP \$ 27902.15 informed MR wong
(Red. \$ 23372.88, 45%)

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 9

1) _____
Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$ _____) S + RS, SI

: Interview (\$ _____) Photos

: Tech. Invs (\$ _____) Others

: Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	727G
Vehicle Details	
Vehicle No.:	SBG3333J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4DR 1.5 AT M-HYBRID ELEGANCE
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	P520614652
Chassis No.:	JM6BP2SAAK1100909
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$24,319.00
Original Registration Date:	15 Aug 2019
First Registration Date:	15 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$16,047.00 <i>823</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2029
PARF Rebate Amount:	\$11,232.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,725.00
COE Rebate Amount:	\$15,605.00
Total Rebate Amount:	\$26,837.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 07 Nov 2024

OK



Mazda 3 Mild Hybrid 1.5A Elegance Sunroof **\$86,800** \$15,410 /yr 24-Dec-2019 (5yrs 1mth COE left) 56,339 km 1,496 cc

Instl. \$1,138 /mth 1 Owner Petrol-Electric

1 owner high specification and high PARF value elegance unit! Extremely well maintained interior exterior! New facelift model and fuel efficient with very responsive drive. Full loan monthly only cost \$1,500++. 100% loan or bank loan available. STA evaluation or Vicom inspection welcomed. Trade in available. Faster contact us today to arrange a non obligatory viewing and test drive appointment.

Carteala Pte Ltd|Posted 25-Oct-2024

Compare



Mazda 3 Mild Hybrid 1.5A Classic **\$76,800** \$14,710 /yr 30-Aug-2019 (4yrs 9mths COE left) 67,366 km 1,496 cc

Instl. \$1,071 /mth 2 Owners Petrol-Electric

Tip Top sunlight white for this unit, good fuel consumption and low maintenance mild hybrid unit, new 6 mths road tax, 0 wear & tear required. high trade in quotation available! Full loan/Bank loan available too! Ring us up to view!

Carteala Pte Ltd|Posted 24-Oct-2024

Compare

ADVERTISING



Mazda 3 Mild Hybrid 1.5A Elegance Sunroof **\$86,800** \$15,430 /yr 24-Dec-2019 (5yrs 1mth COE left) 73,022 km 1,496 cc

Instl. \$1,138 /mth 1 Owner Petrol-Electric

1 owner unit! Mazda 3 Sedan transforms through a design evocative of a single flowing brushstroke. With its air of refined individuality, this sleek and elegant statement of sophisticated dignity connects on a deeper, more mature level. Inspiring powerful impressions of understated grace and beauty that speak directly to the emotions!

SWheels Auto Pte Ltd|Posted 17-Oct-2024

Compare



Mazda 3 HB 1.5A Sunroof **\$62,800** \$13,010 /yr 18-Jan-2019 (4yrs 2mths COE left) 77,949 km 1,496 cc

Instl. \$988 /mth 3 Owners

1 year warranty. In-house financing options available. Buy with a peace of mind. Low mileage. 100% genuine mileage. Well maintained. Immaculate condition. All trade in welcome.

GOwheeler Pte Ltd|Posted 12-Oct-2024

Compare

Compare



QUOTATION

P/P # 27902-15

Not Allowed as means call by to be pke before only. 9 days. P/P # 27902-15

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 1
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	CHINA TAIPING TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE FRT BUMPER, GRILLE TOP, BONNET, FRT FENDER RH, FRT FENDER LH & FRT SUPPORT PANEL.	792	4.5	3564	4,410.00	S
SUB	AND ALL ACCIDENT AFFECTED AREA. TO RESPRAY FRT BUMPER, GRILLE TOP, BONNET, FRT FENDER RH, FRT FENDER LH, FRT REINFORCEMENT, A PILLAR LH & FRT DOOR LH.	758		3204	5,400.00	S
SUB	TO SUPPLY NUMBER PLATE.			320	70.00	S
SUB	TO TRANSFER FRONT SENSORS.			180	330.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.			150	250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			180	300.00	S
SUB	SUNDRIES			20	50.00	S
	BCKA-50-031EBIFRT BUMPER BP	1.00	994.32	*NO STOCK	994.32	S ✓
	C274-50-133 NUT,CLIP	10.00	2.36	*NO STOCK	23.60	S ✓

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

LKK Auto Consultants hence notify the Repairer of the following:

- No survey before/after spray painting
- No display damaged price, in a roadway
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 2
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BDWH-50-2G1	RUBBER,SEAL <i>neu</i>	2.00	7.42	*NO STOCK	14.84	S ✓
BCKA-50-2G1A	RUBBER,SEAL <i>neu</i>	2.00	8.52	STOCK	17.04	S ✓
GD7A-50-EA1	FASTENER <i>neu</i>	2.00	2.62	*NO STOCK	5.24	S ✓
BCKA-50-C11A	COVER RHF LAMP BP <i>neu</i>	1.00	23.52	*NO STOCK	23.52	S ✓
BCKA-50-C21A	COVER LHF LAMP BP <i>neu</i>	1.00	23.52	*NO STOCK	23.52	S X
BCWB-50-170B	HOLDER,LICENSE PLATE BP <i>Dis</i>	1.00	88.34	*NO STOCK	88.34	S ✓
BCKA-50-0S0B	STIFF 'A' BUMPER BP HB <i>neu</i>	1.00	87.32	*NO STOCK	87.32	S ✓
BCKC-50-1C1A	PLATE,SET BP <i>neu</i>	1.00	9.28	*NO STOCK	9.28	S ✓
BCKA-50-1T4A	GARNISH(C)F.BUMPER BP <i>neu</i>	1.00	11.13	*NO STOCK	11.13	S ✓
BCKA-50-A20B	GUIDE RHF AIR BP <i>neu</i>	1.00	78.22	STOCK	78.22	S X
S51S-51-833	RIVET,SPLASH SHIELD <i>neu</i>	6.00	3.12	STOCK	18.72	S ✓
TK21-50-355	RIVET <i>neu</i>	4.00	7.42	*NO STOCK	29.68	S ✓
BCKB-50-A20B	GUIDE LHF AIR BP <i>neu</i>	1.00	78.22	*NO STOCK	78.22	S X
N243-50-0Z1	GROMMET,SCREW <i>neu</i>	2.00	4.64	*NO STOCK	9.28	S ✓
BCKA-50-0U5	GROMMET,SCREW'B' <i>neu</i>	1.00	2.36	*NO STOCK	2.36	S ✓
BDGF-50-0T6B	RETAINER'A'FRT BUMPER BP <i>neu</i>	1.00	11.13	*NO STOCK	11.13	S X
BCKA-50-0T0A	RETAINER RHF BUMPER BP <i>neu</i>	1.00	23.52	*NO STOCK	23.52	S X
BCKA-50-0U0A	RETAINER LHF BUMPER BP <i>neu</i>	1.00	23.52	*NO STOCK	23.52	S X
BCKA-50-1U1A	SEAL RHF GRILL BP <i>neu</i>	1.00	15.77	STOCK	15.77	S X
BCKA-50-1V1A	SEAL LHF GRILL BP <i>neu</i>	1.00	15.77	STOCK	15.77	S X

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

TRANS EUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Eurokars Group Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899
 23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 3
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status		Gross	GST
				SGD	*NO STOCK	amount	Code
BDGF-50-2G2	SEAL RUBBER <i>PN X</i>	2.00	2.79	*NO STOCK		5.58	S X
BCJH-50-070B	REINF FRT BUMPER BP <i>PN X</i>	1.00	621.53	*NO STOCK		621.53	S X
BOJ8-67-UC6	BRACKET B/SENSOR BP <i>PN ✓</i>	2.00	26.89	*NO STOCK		53.78	S ✓
BOL2-67-UC5	13RETAINER BP <i>PN ✓</i>	1.00	66.93	*NO STOCK		66.93	S ✓
BOL7-67-UC5	53RETAINER BP <i>PN ✓</i>	1.00	66.93	*NO STOCK		66.93	S ✓
BOM5-67-UC5	RETAINER LHSF, SENSOR BP <i>PN ✓</i>	1.00	4.64	*NO STOCK		4.64	S ✓
BOM6-67-UC5	RETAINER RHCF, SENSOR BP <i>PN ✓</i>	1.00	4.64	STOCK		4.64	S ✓
BOJ8-67-UC1	2MSENSOR FRT BUMPER BP <i>SVCX</i>	2.00	217.88	STOCK		435.76	S X
BOJ7-67-UC1	SENSOR,ULTRASONIC BP <i>Mol function ipc</i>	1.00	217.88	*NO STOCK		435.76	S X
BDGF-50-154A	BRACKET RH BP <i>PN ✓</i>	1.00	15.77	*NO STOCK		15.77	S ✓
BDGF-50-164A	BRACKET LH BP <i>PN ✓</i>	1.00	15.77	STOCK		15.77	S ✓
BCKA-50-A11A	COVER,TOWING HOOK- BP <i>PN ✓</i>	1.00	12.98	*NO STOCK		12.98	S ✓
BCKA-50-EM1	TAPE,PROTECTOR <i>PN ✓</i>	2.00	7.42	*NO STOCK		14.84	S ✓
BOL5-67-A10	CORD FRT. BUMPER BP <i>PN ✓</i>	1.00	573.91	*NO STOCK		573.91	S ✓
BCKA-50-7J0C	MOULD RH F LWR BP <i>CNA ✓</i>	1.00	341.95	*NO STOCK		341.95	S ✓
BCKA-50-7K0C	MOULD LH GRILLE BP <i>CNA ✓</i>	1.00	341.95	*NO STOCK		341.95	S ✓
BCKA-50-711A	GRILLE,RADIATOR BP <i>CNA ✓</i>	1.00	187.03	*NO STOCK		187.03	S ✓
BCKC-50-1U2A	PLATE(R),SEAL-F. BUM BP <i>PN ✓</i>	1.00	15.77	*NO STOCK		15.77	S ✓
BCKC-50-1V2A	PLATE(L),SEAL-F.BUMP BP <i>PN X</i>	1.00	15.77	*NO STOCK		15.77	S X
BDGK-50-721A	BRACKET (C)BP <i>PN X</i>	1.00	28.83			28.83	S X

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



Showrooms & Service Centres :
 5 Ubi Close Singapore 408605
 Sales Tel: 6395 8888 Service Tel: 6395 8899
 Sales Fax: 68461700 Service Fax: 6744 9402
 23 Leng Kee Road Singapore 159095
 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 4
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price		Stk/Status	Gross	GST
			SGD	SGD		amount	Code
BCKB-51-730A	MASCOT FRT W/SENSOR BP	1.00	809.32	809.32	STOCK	809.32	S ✓
G46L-50-EB1	CLIP	2.00	4.64	9.28	STOCK	9.28	S ✓
GSH7-50-EB1	CLIP	1.00	9.28	9.28	STOCK	9.28	S ✓
BOJ9-67-RC0	CAMERA,FRONT BP	1.00	1,223.07	1,223.07	*NO STOCK	1,223.07	S ✓
BCKA-50-ES1B	GROMMET	4.00	3.71	14.84	*NO STOCK	14.84	S ✓
BCKB-50-7E0D1	GRILLE,RADIATOR-UPP BP	1.00	632.40	632.40	STOCK	632.40	S ✓
TK21-50-355	RIVET	10.00	7.42	74.20	STOCK	74.20	S ✓
S51S-51-833	RIVET,SPLASH SHIELD	16.00	3.12	49.92	STOCK	49.92	S ✓
BCKA-50-150A	BRACKET RHF BUMPER-LWR BP	1.00	67.69	67.69	STOCK	67.69	S ✓
BCKA-50-160A	BRACKET LHF BUMPER-LWR BP	1.00	67.69	67.69	*NO STOCK	67.69	S X
BCKV-51-030B	HEADLAMP RH BP ELEGANCE	1.00	4,179.56	4,179.56	STOCK	4,179.56	S ✓
BCKV-51-040B	HEADLAMP LH BP ELEGANCE	1.00	4,179.56	4,179.56	*NO STOCK	4,179.56	S ✓
BCKA-56-145A	CLIP	10.00	6.49	64.90	*NO STOCK	64.90	S ✓
BCY0-52-31XD	BONNET BP	1.00	1,189.44	1,189.44	*NO STOCK	1,189.44	S ✓
BCJH-56-681	INSULATOR,BONNET BP	1.00	191.84	191.84	STOCK	191.84	S X
TD11-56-694	FASTENER,BONNET	11.00	2.36	25.96	*NO STOCK	25.96	S ✓
BCJH-52-410	HINGE(R),BONNET BP	1.00	58.75	58.75	*NO STOCK	58.75	S ✓
BCJH-52-420	HINGE LHS, BONNET	1.00	63.55	63.55	*NO STOCK	63.55	S ✓
BCJH-56-770A	WEATHERSTRIP,BONNET BP	1.00	67.35	67.35	*NO STOCK	67.35	S ✓
BCJH-56-742	FASTENER	24.00	2.36	56.64	*NO STOCK	56.64	S ✓

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



Showrooms & Service Centres :
 5 Ubi Close Singapore 408605
 Sales Tel: 6395 8888 Service Tel: 6395 8899
 Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 5
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status		Gross amount	GST Code
				SGD	*NO STOCK		
BCJH-56-750	WEATHERSTRP,BONNET-FRT BP	1.00	24.95	STOCK		24.95	S ✓
BC1D-58-762	FASTENER	9.00	2.70	*NO STOCK		24.30	S ✓
BCJH-56-651A	STAY,LOCK-BONNET BP	1.00	35.15	*NO STOCK		35.15	S ✓
L206-56-652A	HOLDER,BONNET STAY KE	1.00	10.20	*NO STOCK		10.20	SX
BCJH-56-627B	PROTECT,LOCK-BONNET BP	1.00	22.93	*NO STOCK		22.93	SX
BCKT-56-620	LOCK,BONNET BP	1.00	197.99	*NO STOCK		197.99	S ✓
BOJ8-56-720	WIRE RELEASE BONNET BP	1.00	38.19	*NO STOCK		38.19	S X
BCJH-56-731	CLIP,WIRE-BONNET	3.00	2.36	*NO STOCK		7.08	S X
BCKA-56-130	GUARD(R),MUD BP	1.00	83.95	*NO STOCK		83.95	SX
BCKA-56-140	GUARD(L),MUD BP	1.00	83.95	*NO STOCK		83.95	SX
BFWM-56-114	GUARD MUD RHF BP	1.00	230.95	*NO STOCK		230.95	SX
BFWM-56-115	GUARD MUD LHF BP	1.00	242.49	STOCK		242.49	SX
B45A-56-146A	FASTENER	44.00	2.36	*NO STOCK		103.84	SX
BCJH-52-110	RHF FENDER SN BP	1.00	476.81	*NO STOCK		476.81	SX
BCJH-52-210	PANEL(L),FENDER-FRT BP	1.00	476.81	STOCK		476.81	SX
GJ21-68-885B02	FASTENER	6.00	2.36	*NO STOCK		14.16	SX
BCJH-52-140	STAY RHF FENDER BP	1.00	48.22	*NO STOCK		48.22	SX
BCJH-52-240	STAY(L),FENDER	1.00	52.77	*NO STOCK		52.77	SX
BCJH-53-150B	MEMBER,SHROUD-UPPER BP	1.00	159.14	*NO STOCK		159.14	S ✓
BCPT-53-100G	PANEL,SHROUD	1.00	1,171.32			1,171.32	S ✓

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 6
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross	GST
					amount	Code
			SGD	*NO STOCK	SGD	
BCJH-52-15Y	STAY,LOCK BP	1.00	51.33	*NO STOCK	51.33	S ✓
BCKC-50-A20B	GUIDE,AIR BP	1.00	140.50	STOCK	140.50	S X
KD45-50-EA1	FASTENER	4.00	2.36	*NO STOCK	9.44	S X
BCKA-50-7M0A	INTAKE,AIR BP	1.00	224.96	STOCK	224.96	S ✓
GD7A-50-EA1	FASTENER	3.00	2.62	*NO STOCK	7.86	S ✓
BCKB-56-11Y	COVER,UNDER-FRT BP	1.00	228.76	*NO STOCK	228.76	S X
BDGF-66-78YD	HORN & BRACKET-HIGH BP	1.00	178.10	STOCK	178.10	S X
KD35-66-79YA	HORN,ELECT LH S/ACTIV	1.00	76.28	*NO STOCK	76.28	S X
BCKA-67-481	TANK,WASHER BP	1.00	59.09	*NO STOCK	59.09	S X
BDGF-61-480A	CONDENSER BP	1.00	1,085.18	STOCK	1,085.18	S ✓
11-NAC9-15-00	COOLANT LONG LIFE 4 LTS	1.00	54.80	*NO STOCK	54.80	S ✓
PAF1-15-200	RADIATOR BP	1.00	1,144.94	*NO STOCK	1,144.94	S ✓
PAF2-15-025	FAN ELECTRIC BP	1.00	1,193.24	STOCK	1,193.24	S X
PAF1-15-351	TANK,SUB-RAD BP	1.00	66.76	*NO STOCK	66.76	S X
P5E1-13-100	MANIFOLD INLET BP	1.00	1,024.16	*NO STOCK	1,024.16	S X
P5E2-13-200A	DUCT FRESH AIR BP	1.00	107.97	*NO STOCK	107.97	S X
P5E2-13-195A	CHAMBER RESONANCE BP	1.00	57.15	*NO STOCK	57.15	S X
P5E2-13-3AYA	CASE AIR CLEANER BP	1.00	68.78	STOCK	68.78	S X
S801-13-3A0	AIR FILTER BP	1.00	62.00	*NO STOCK	62.00	S X
P5E2-13-3AXA	COVER AIR CLEANER BP	1.00	74.68		74.68	S X

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 7
 DOCUMENT NO.: 1564
 DOCUMENT DATE: 05/11/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: I
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BEWT-67-010D	HARNES FRT/RR WIRING BP	1.00	9,451.92	*NO STOCK	9,451.92	SX
BON2-67-XA0E	SENSOR,RADAR-FRONT BP	1.00	3,442.23	*NO STOCK	3,442.23	SX

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-		-	51,275.03	4,614.75	55,889.78
Surcharge	S	9.00%	51,275.03	4,614.75	0.00	0.00	0.00
Labour							
Menus							
Amount Due					51,275.03	4,614.75	55,889.78

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
 No.

Date: _____ Customer signature _____ Authorised signature _____

TRANS EUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Eurokars Group Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899
 23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
 CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

PAGE NO.: 5
 DOCUMENT NO.: 1631
 DOCUMENT DATE: 03/12/2024
 POS ID: MU
 PRINTED BY: Wong Chun Wei
 SERVICE ADV:
 CSP/OP CODE: Wong Chun Wei
 DEPT: |
 WIP NO.: 21680
 REF. NO.:
 DATE IN:
 EXT. WTY: 14/08/2024
 MILEAGE: 0

CONTACT NO.: 6389 6111
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID ELE
 CHASSIS NO.: JM6BP2SAAK1100909
 ENGINE NO.: P520614652
 REG NO.: SBG3333J
 REGN DATE: 15/08/2019

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BCPT-53-100G	PANEL,SHROUD	1.00	1,171.32	*ISSUED	1,171.32	S ✓
BCKA-50-C11A	COVER RHF LAMP BP	1.00	23.52	*ISSUED	23.52	S ✓
B0J7-67-UC1	SENSOR,ULTRASONIC BP	1.00	217.88	*ISSUED	217.88	S ✓
BDGF-50-154A	BRACKET RH BP	1.00	15.77	*ISSUED	15.77	S ✓
BDGF-50-164A	BRACKET LH BP	1.00	15.77	*ISSUED	15.77	S ✓
B0L5-67-A10	CORD FRT. BUMPER BP	1.00	573.91	*ISSUED	573.91	S ✓
BCKC-50-1U2A	PLATE(R),SEAL-F. BUM BP	1.00	15.77	*ISSUED	15.77	S ✓
B0J9-67-RC0	CAMERA,FRONT BP	1.00	1,223.07	*ISSUED	1,223.07	S ✓
BCKA-50-150A	BRACKET RHF BUMPER-LWR BP	1.00	67.69	*ISSUED	67.69	S ✓
BCKT-56-620	LOCK,BONNET BP	1.00	197.99	*ISSUED	197.99	S ✓
BCJH-52-15Y	STAY,LOCK BP	1.00	51.33	*ISSUED	51.33	S ✓
BCKA-50-7M0A	INTAKE,AIR BP	1.00	224.96	*ISSUED	224.96	S ✓
GD7A-50-EA1	FASTENER	3.00	2.62	*ISSUED	7.86	S ✓
BDGF-61-480A	CONDENSER BP	1.00	1,085.18	*ISSUED	1,085.18	S ✓
11-NAC9-15-00	COOLANT LONG LIFE 4:LTS	1.00	54.80	*ISSUED	54.80	S ✓
PAF1-15-200	RADIATOR BP	1.00	1,144.94	*ISSUED	1,144.94	S ✓
PE01-15-031	LABEL,CAUTION	1.00	2.36	*ISSUED	2.36	S ✓
KF49-61-439	LABEL,CAUTION	1.00	2.36	*ISSUED	2.36	S ✓
BDMC-67-ZB6	LABEL-BATTERY BP	1.00	2.36	*ISSUED	2.36	S ✓
11-BCJH-56-651	STAY,LOCK-BONNET BP	1.00	35.15	*ISSUED	35.15	S ✓

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

TRANS EUROKARS Corporate Head Office : Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
 Eurokars Group: Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899
 23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417