



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLA 8607A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	\$1,452.00	\$0.00
1	FRONT RH DOOR HANDLE	NOT NECESSARY	\$254.00	\$0.00
1	FRONT RH DOOR LOCK	NOT NECESSARY	\$313.00	\$0.00
2	FRONT RH DOOR HINGE	NOT NECESSARY	\$150.00	\$0.00
1	FRONT RH DOOR WEATHERSTRIP	NOT NECESSARY	\$385.00	\$0.00
1	FRONT LH DOOR MOULDING	NOT NECESSARY	\$120.00	\$0.00
1	ROCKER PANEL RH	NOT NECESSARY	\$425.90	\$0.00
1	REAR RH DOOR	TO REPAIR SEE LABOUR	\$853.00	\$0.00
1	REAR RH DOOR HANDLE	NOT NECESSARY	\$254.00	\$0.00
1	REAR RH DOOR LOCK	NOT NECESSARY	\$313.00	\$0.00
2	REAR RH DOOR HINGE	NOT NECESSARY	\$150.00	\$0.00
1	REAR RH DOOR WEATHERSTRIP	NOT NECESSARY	\$385.00	\$0.00
1	REAR RH DOOR GLASS	NOT NECESSARY	\$485.60	\$0.00
1	REAR RH DOOR MOULDING	NOT NECESSARY	\$120.00	\$0.00
1	REAR RH FENDER	TO REPAIR SEE LABOUR	\$1,854.00	\$0.00
1	REAR RH FENDER INNER SHIELD	NOT NECESSARY	\$220.00	\$0.00
	LESS 10.00 / 20.00% DISCOUNT		(\$773.45)	\$0.00
			\$6,961.05	\$0.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT DOOR CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET REAR DOOR CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET RIM (SN)	TO REPAIR SEE LABOUR	\$1,200.00	\$0.00
1	JOINT SEALANT (SN)	NOT NECESSARY	\$120.00	\$0.00
			\$1,470.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK FRONT AND REAR LH DOOR WING AND LIGHTING SYSTEM	NOT NECESSARY	\$200.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIT FRONT AND REAR LH DOOR LINING, TRIM AND GARNISH	NOT NECESSARY	\$300.00	\$0.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR, REAR RH DOOR AND REAR RH FENDER		\$1,200.00	\$400.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,200.00	\$600.00
	APPLY ANTI RUST ON AFFECTED AREAS	NOT NECESSARY	\$100.00	\$0.00
			\$3,000.00	\$1,000.00
GRAND TOTAL			\$11,431.05	\$1,000.00
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			\$1,000.00
Report Ref No: CS/INC24110112/Uqp3e2				

TOTAL FOR SPARE PARTS: \$ 8,431.05 \$ 0.00
TOTAL FOR LABOUR : \$ 3,000.00 \$ 1,000.00
TOTAL REPAIR COST: \$ 11,431.05 \$ 1,000.00

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.