

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SANDY KAU LI PING
BLK 336 SEMBAWANG CRESCENT #07-184
SINGAPORE 750336

Contact : 91500353 91518582

TP INC
Veron

TAX INVOICE

Repair Code : CLM16339

Date in : 24/06/2024

Vehicle Num. : SNK280J

Model : TOYOTA CAMRY HYBRID ASCENT SPORT 2.5 CVT

Chassis/Eng# : JTNBA3HK603005615/A25A5563945

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	1705.90	✓ 1,705.90
REAR BOOTLID 'HYBRID' EMBLEM <i>new</i>	1	74.20	✓ 74.20
REAR BOOTLID 'LOGO' EMBLEM <i>new</i>	1	76.60	✓ 76.60
REAR BOOTLID 'TOYOTA' EMBLEM <i>new</i>	1	76.00	✗ 76.00
REAR BOOTLID HINGES COVER L/R <i>new</i>	2	120.50	✗ 241.00
REAR BOOTLID HINGES L/R <i>new</i>	2	243.80	✗ 487.60
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	32.10	✗ 64.20
REAR BOOTLID INNER TRIM GARNISH <i>new</i>	1	441.60	✗ 441.60
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	677.60	✗ 677.60
REAR BOOTLID OUTER COVER <i>new</i>	1	230.80	✗ 230.80
REAR BOOTLID OUTER COVER 'CAMRY' EMBLEM <i>new</i>	1	97.80	✗ 97.80
REAR BOOTLID REFLECTOR L/R <i>new</i>	2	920.70	✗ 1,841.40
REAR BOOTLID WEATHER STRIP <i>new</i>	1	264.00	✗ 264.00
REAR BUMPER <i>Dented</i>	1	983.40	✓ 983.40
REAR BUMPER LOWER OUTER MOULDING L/R <i>new</i>	2	130.70	✗ 261.40
REAR BUMPER OUTER SIDE GARNISH L/R <i>new</i>	2	41.00	✗ 82.00
REAR BUMPER REFLECTOR L/R <i>new</i>	2	81.80	✗ 163.60
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	456.50	✓ 456.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SANDY KAU LI PING
BLK 336 SEMBAWANG CRESCENT #07-184
SINGAPORE 750336

Contact : 91500353 91518582

TAX INVOICE

Repair Code : CLM16339

Date in : 24/06/2024

Vehicle Num. : SNK280J

Model : TOYOTA CAMRY HYBRID ASCENT SPORT 2.5 CVT

Chassis/Eng# : JTNBA3HK603005615/A25A5563945

REAR BUMPER REVERSE SENSOR <i>new</i>	4	498.90	+	1,995.60
REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	4	25.00	+	100.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	25.50	+	102.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	185.50	+	371.00
REAR BUMPER SPONGE <i>new</i>	1	121.90	X	121.90
REAR END PANEL <i>new</i>	1	953.20	+	953.20
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	452.30	+	452.30
REAR END PANEL INNER TOP GARNISH	1	314.20	+	314.20
REAR TAILLAMP L/R <i>new</i>	2	1331.80	+	2,663.60
REAR TAILLAMP LOWER COVER L/R <i>new</i>	2	89.90	+	179.80
REAR TAILLAMP LOWER GARNISH COVER L/R	2	41.00		82.00
Subtotal before discount				15,561.20
Percentage discount 25%				3,890.30
Sub-total 1				11,670.90
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	30.00	X	30.00
REAR BOOTLID NUMBER PLATE <i>new</i>	1	25.00	+	25.00
REAR BOOTLID NUMBER PLATE FRAME <i>new</i>	1	50.00	+	50.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SANDY KAU LI PING
BLK 336 SEMBAWANG CRESCENT #07-184
SINGAPORE 750336

Contact : 91500353 91518582

TAX INVOICE

Repair Code : CLM16339
Date in : 24/06/2024
Vehicle Num. : SNK280J
Model : TOYOTA CAMRY HYBRID ASCENT SPORT 2.5 CVT
Chassis/Eng# : JTNBA3HK603005615/A25A5563945

REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	40.00
Subtotal before discount			225.00
Percentage discount 0%			0.00
Sub-total 2			225.00
Parts-total			11,895.90

LABOUR

To transfer rear bootlid mechanism lock outer handle reflector
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

Labour Total 2,320.00
Parts & Labour Total 14,215.90

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date:

page 3

3.6K

Admin
n/s 26/06/24
03 Days
Total: 4508.05
n/s: 3.6K