

Company Reg No: 202136904Z

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 05.11.2024

TO	: INCOME MOTOR CLAIMS DEPTS
VEHICLE NO	: SH105P
MODEL	: MAN RR8
DATE OF ACCIDENT	: 03.11.2024
TIME OF ACCIDENT	: 10:00 HOURS

WMARR8ZZXLFO12593

Xiao Chan.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR CAP <i>Cracked</i>	2	\$ 8,600.00	\$ 17,200.00
2	REAR CAP REFLECTORS <i>Not new cracked</i>	2	\$ 586.00	\$ 1,172.00
3	REAR CAP EMBLEM 'MAN' <i>Not new</i>	1	\$ 183.00	\$ 183.00
4	REAR WINDSCREEN GLASS <i>New</i>	1	\$ 8,350.00	\$ 8,350.00
5	REAR ENGINE COMPARTMENT DOOR COVER <i>Distorted</i>	1	\$ 3,568.00	\$ 3,568.00
6	REAR ENGINE COMPARTMENT DOOR FRAME <i>Distorted</i>	1	\$ 2,155.00	\$ 2,155.00
7	REAR ENGINE COMPARTMENT OUTER HANDLE <i>cracked</i>	1	\$ 155.00	\$ 155.00
8	REAR ENGINE COMPARTMENT ABSORBERS <i>2nd</i>	2	\$ 484.00	\$ 968.00
9	REAR ENGINE COMPARTMENT HINGES <i>Not new</i>	2	\$ 270.00	\$ 540.00
10	REAR NUMBER PLATE LAMP <i>Not new</i>	1	\$ 286.00	\$ 286.00
11	TAILLAMP UPPER (SMALL) <i>cracked</i>	2	\$ 975.00	\$ 1,950.00
12	TAILLAMP (BIG) <i>cracked</i>	2	\$ 2,380.00	\$ 4,760.00
13	REAR BUMPER <i>Distorted</i>	1	\$ 1,865.00	\$ 1,865.00
14	REAR BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 4,580.00	\$ 4,580.00
15	REAR BUMPER REINFORCEMENT BRACKET <i>Best</i>	2	\$ 680.00	\$ 1,360.00
16	REAR CROSS MEMBER <i>Best</i>	1	\$ 4,350.00	\$ 4,350.00
17	PILLAR SIDE SUPPORT <i>Repair</i>	2	\$ 980.00	\$ 1,960.00
18	AIR CLEANER BOX <i>cracked</i>	1	\$ 3,850.00	\$ 3,850.00
19	POWER STEERING TANK ASSY <i>cracked</i>	1	\$ 1,862.00	\$ 1,862.00
20	POWER STEERING TANK BRACKET <i>Not new</i>	1	\$ 580.00	\$ 580.00
21	ENGINE OIL SPARE TANK ASSY <i>cracked</i>	1	\$ 1,700.00	\$ 1,700.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SH105P**
 MODEL : **MAN RR8**
 DATE OF ACCIDENT : 03.11.2024
 TIME OF ACCIDENT : 10:00 HOURS

22	ENGINE OIL SPARE TANK BRACKET <i>new</i>	1	\$ 680.00	\$ 680.00
23	ALTERNATOR ASSY <i>cracked</i>	1	\$ 2,380.00	\$ 2,380.00
24	DIESEL PUMP ASSY <i>cracked</i>	1	\$ 5,680.00	\$ 5,680.00
25	COOLER CONTAINER <i>defunct</i>	1	\$ 1,640.00	\$ 1,640.00

TOTAL PRICE \$ 73,774.00
 LESS 10% \$ 7,377.40
SUB TOTAL PRICE \$ 66,396.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 200.00	\$ 200.00
3	REAR WINDSCREEN GLASS INNER SHIELD <i>new</i>	1	\$ 180.00	\$ 180.00
4	50KM/H STICKER <i>new</i>	1	\$ 40.00	\$ 40.00
5	80/90 KM/H STICKER <i>new</i>	1	\$ 80.00	\$ 80.00
6	POWER STEERING OIL <i>new</i>	1	\$ 480.00	\$ 480.00
7	ENGINE OIL	1	\$ 680.00	\$ 680.00
8	COOLANT	1	\$ 480.00	\$ 480.00

TOTAL \$ 2,220.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 3,200.00	2000
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,400.00	1400
3	TUFF COAT	\$ 480.00	100
4	WIRING AND BULB CHECK	\$ 180.00	80
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 1,000.00	X
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 180.00	X

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SH105P**
 MODEL : **MAN RR8**
 DATE OF ACCIDENT : 03.11.2024
 TIME OF ACCIDENT : 10:00 HOURS

7	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 450.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	280

TOTAL

\$8,070.00

3860

ESTIMATE REPORT

TOTAL PARTS COST : \$ 68,616.60
 TOTAL LABOUR COST : \$ 8,070.00
 TOTAL REPAIR COST : \$ 76,686.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

Adrian Lj

H/S 06/11/24

14 Days.

Total: 35199.30

L/S: 28150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: