

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

limited
rep.

Not Authorized
near
may
7/11/24
1/58
telephone after rep.
10 day.

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
IOB Building #04-05
Singapore 049711

Tel: 63476100

Fax: 62244174, 62257743

Attn: Motor Claim Department

Your Ref No: TP 1124-8339

Claim Type: Third Party

Accident Date: 03 November 2024

TP Veh Reg No: SLZ9349G

Estimate No: EST1512002

Date: 04 Nov 2024

Policy No: MT/00358436/07

Veh Reg No: SKZ3780U

Make/Model: MITSUBISHI ASX 2.0
CVT ABS D/AIRBAG
2WD

Chassis No: JMFXTGA2WFZC09058

Engine No: 4B11QT6375

Reg. Date: 21 Jan 2016

Estimate Repair Cost to Vehicle No: SKZ3780U

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 FRONT BUMPER <i>DD</i>	952.00	1 PC	952.00	✓
2 FRONT BUMPER CLIPS <i>ner</i>	4.90	10 PC	49.00	✓
3 FRONT BUMPER TOP GRILLE <i>son</i>	280.00	1 PC	280.00	✓
4 FRONT BUMPER TOP GRILLE LOGO <i>ner</i>	49.00	1 PC	49.00	✓
5 FRONT BUMPER LOWER GRILLE <i>twi</i>	322.00	1 PC	322.00	✓
6 FRONT GRILLE SURROUND CHROME <i>one</i>	815.00	1 PC	815.00	✓
7 FRONT BUMPER FOAM	22.00	1 PC	22.00	?
8 FRONT BUMPER REINFORCEMENT (BIG)	493.00	1 PC	493.00	?
9 FRONT BUMPER BEAM (SMALL)	73.00	1 PC	73.00	?
10 FRONT BUMPER FOGLAMP - LH/RH <i>17</i>	435.00	2 PC	870.00	X
11 FRONT BUMPER FOGLAMP COVER - LH/RH <i>17</i>	55.00	2 PC	110.00	X
12 FRONT BUMPER DAY LAMP - LH/RH <i>17</i>	710.00	2 PC	1,420.00	X
13 HEADLAMP UNIT - LH/RH	1,015.00	2 PC	2,030.00	?
14 HEADLAMP TOP PANEL - LH/RH <i>R</i>	87.00	2 PC	174.00	X
15 SUPPORT PANEL - TOP <i>but</i>	508.00	1 PC	508.00	✓
16 SUPPORT PANEL - LOWER <i>R</i>	348.00	1 PC	348.00	X
17 SUPPORT PANEL TOP GARNISH <i>twi</i>	138.00	1 PC	138.00	✓
18 A/C CONDENSER	1,087.00	1 PC	1,087.00	?
19 A/C CONDENSER SIDE AIR GUIDE - LH/RH	79.00	2 PC	158.00	?
20 A/C CONDENSER TOP AIR GUIDE	123.00	1 PC	123.00	?
21 A/C FAN BLADE	73.00	1 PC	73.00	?
22 A/C FAN MOTOR	479.00	1 PC	479.00	?
23 A/C FAN COWLING	275.00	1 PC	275.00	?
24 RADIATOR	1,189.00	1 PC	1,189.00	?
25 RADIATOR FAN BLADE	73.00	1 PC	73.00	?
26 RADIATOR FAN MOTOR	479.00	1 PC	479.00	?
27 BONNET <i>but/bul</i>	942.00	1 PC	942.00	✓
28 BONNET HINGE - LH/RH <i>R</i>	88.00	2 PC	176.00	X
29 BONNET LOCK <i>twi</i>	116.00	1 PC	116.00	✓
30 BONNET SIDE RUBBER - LH/RH <i>ner</i>	28.00	2 PC	56.00	X
31 BONNET INSULATOR <i>17</i>	149.00	1 PC	149.00	X
32 BONNET INSULATOR CLIPS <i>17</i>	4.90	10 PC	49.00	?
33 AIRDUCT	276.00	1 PC	276.00	?
34 HORN - LH/RH	160.00	2 PC	320.00	?
35 REAR BUMPER- <i>DD</i>	878.00	1 PC	878.00	✓
36 REAR BUMPER SIDE RETAINER - LH/RH <i>but</i>	38.00	2 PC	76.00	✓
37 REAR BUMPER CLIPS <i>ner</i>	4.90	10 PC	49.00	✓
38 REAR BUMPER TOW COVER <i>but 17</i>	26.00	1 PC	26.00	X
39 REAR BUMPER CENTER COVER <i>17</i>	55.00	1 PC	55.00	X
40 REAR BUMPER REFLECTOR - LH/RH <i>17</i>	38.00	2 PC	76.00	X
41 REAR BUMPER REINFORCEMENT	348.00	1 PC	348.00	?
42 REAR END PANEL	363.00	1 PC	363.00	?
43 REAR END PANEL TOP GARNISH-	160.00	1 PC	160.00	?
44 TAILGATE <i>DD</i>	1,089.00	1 PC	1,089.00	✓
45 TAILGATE HINGE - LH/RH <i>17</i>	70.00	2 PC	140.00	X
46 TAILGATE GLASS MOULDING <i>ner</i>	73.00	1 PC	73.00	✓
47 TAILGATE "ASX" WORDINGS <i>ner</i>	65.00	1 PC	65.00	✓
48 TAILGATE "MIVEC" WORDINGS <i>ner</i>	87.00	1 PC	87.00	✓

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

49	TAILGATE MITSUBISHI LOGO	58.00	1 PC	58.00	✓
50	TAILGATE LAMP - LH/RH	638.00	2 PC	1,276.00	✓
51	TAILGATE TOP LOCK	464.00	1 PC	464.00	✓
52	TAILGATE LOWER LOCK STRIKER	28.00	1 PC	28.00	✓
53	TAILGATE WEATHERSTRIP	220.00	1 PC	220.00	✓
54	REAR SPARE TYRE TOP BOARD	261.00	1 PC	261.00	✓
				20,465.00	
				Less 10%	-2,046.50
					18,418.50

Special Net					
55	REAR BUMPER SENSOR	200.00	1 PC	200.00	✓
56	SEALANT	20.00	2 PC	40.00	✓
57	SPONGE TAPE	20.00	1 PC	20.00	✓
58	FRONT NUMBER PLATE-	35.00	1 PC	35.00	✓
59	REAR NUMBER PLATE	35.00	1 PC	35.00	✓
				330.00	

Labour					
60	TO KNOCK OUT DENTS ON FENDERS, CUT/WELD FRONT SUPPORT PANEL, REAR END PANEL, REMOVE, REPLACE ACCIDENT PORTIONS-	1,800.00	1 JOB	1,800.00	1200
61	TO RESPRAY PAINT ON ACCIDENT PORTIONS-	1,600.00	1 JOB	1,600.00	1500
62	TO CHECK WIRING-	50.00	1 JOB	50.00	20
63	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00	60
64	TO REMOVE, REPLACE REAR BUMPER SENSOR-	80.00	1 JOB	80.00	30
65	ANTI-RUST-	90.00	1 JOB	90.00	60
66	TO TRANSFER TAILGATE FITTINGS-	100.00	1 JOB	100.00	50
67	TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	120
68	TO REMOVE, REPLACE A/C CONDENSER & REFILL GAS-	120.00	1 JOB	120.00	?
				4,140.00	

Total	22,888.50
Add GST @ 9%	2,059.97
Total Amount Payable SGD	24,948.47

SINGAPORE DOLLAR TWENTY FOUR THOUSAND NINE HUNDRED FORTY EIGHT AND CENTS FORTY SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE