

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SLX 4337J**
 Made : **Subaru**
 Model : **Forester 2.0I-L CVT**
 Chassis No : **JF1SJ5KC5JG105732**

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper / <i>BR</i>	1	\$ 610.50	\$ 610.50
2	Front Bumper Tow Cover <i>X nn</i>	1	\$ 10.20	\$ 10.20
3	Front Bumper Lower Grille <i>X nn</i>	1	\$ 105.00	\$ 105.00
4	Front Bumper Side Retainer RH <i>X nn</i>	1	\$ 42.00	\$ 42.00
5	Front Bumper Side Retainer LH / <i>BR</i>	1	\$ 42.00	\$ 42.00
6	Front Bumper Bracket RH <i>X nn</i>	1	\$ 16.00	\$ 16.00
7	Front Bumper Bracket LH <i>X nn</i>	1	\$ 16.00	\$ 16.00
8	Front Bumper Fog Lamp Garnish RH <i>X nn</i>	1	\$ 48.80	\$ 48.80
9	Front Bumper Fog Lamp Garnish LH <i>X nn</i>	1	\$ 48.80	\$ 48.80
10	Front Bumper Fog Lamp Side Garnish RH <i>X nn</i>	1	\$ 23.00	\$ 23.00
11	Front Bumper Fog Lamp Side Garnish LH <i>X nn</i>	1	\$ 23.00	\$ 23.00
12	Front Bumper Fog Lamp RH <i>X nn</i>	1	\$ 282.00	\$ 282.00
13	Front Bumper Fog Lamp LH <i>X nn</i>	1	\$ 282.00	\$ 282.00
14	Front Bumper Nozzle Cover RH <i>X nn</i>	1	\$ 65.50	\$ 65.50
15	Front Bumper Nozzle Cover LH <i>X nn</i>	1	\$ 65.50	\$ 65.50
16	Front Bumper Nozzle Washer RH <i>X nn</i>	1	\$ 94.10	\$ 94.10
17	Front Bumper Nozzle Washer LH <i>X nn</i>	1	\$ 94.10	\$ 94.10
18	Front Bumper Sponge <i>X nn</i>	1	\$ 142.40	\$ 142.40
19	Front Bumper Reinforcement <i>X nn</i>	1	\$ 325.60	\$ 325.60
20	Front Grille Assembly Upper / <i>nn</i>	1	\$ 170.60	\$ 170.60
21	Front Grille Assembly Lower Chrome Moulding	1	\$ <i>X nn</i> 185.60	\$ 185.60
22	Front Grille Assembly / <i>BR</i>	1	\$ 357.50	\$ 357.50
23	Front Grille Upper Bracket <i>X nn</i>	1	\$ 21.60	\$ 21.60
24	Front Grille Lower Bracket <i>X nn</i>	1	\$ 32.20	\$ 32.20
25	Front Headlamp Assembly RH <i>X nn</i>	1	\$ 2,380.00	\$ 2,380.00
26	Front Headlamp Assembly LH / <i>BR</i>	1	\$ 2,380.00	\$ 2,380.00
27	Front Bonnet <i>X R</i>	1	\$ 916.50	\$ 916.50

28	Front Bonnet Hinge RH	X nn	1	\$	54.40	\$	54.40
29	Front Bonnet Hinge LH	X nn	1	\$	54.40	\$	54.40
30	Front Bonnet Lock Assembly	X nn	1	\$	75.50	\$	75.50
31	Front Bonnet Insulator Centre	X nn	1	\$	169.20	\$	169.20
32	Front Bonnet Insulator RH	X nn	1	\$	47.00	\$	47.00
33	Front Bonnet Insulator LH	X nn	1	\$	47.00	\$	47.00
34	Front Door LH	X nn	1	\$	884.30	\$	884.30
35	Front Fender LH	/ nn	1	\$	327.50	\$	327.50
36	Front Fender Inner Upper Garnish LH	X nn	1	\$	22.50	\$	22.50
37	Front Fender Inner Cowling LH	/ TN	1	\$	131.00	\$	131.00
38	Front Shock Absorber LH	/ nn	1	\$	367.60	\$	367.60
39	Front Lower Arm LH	/ nn	1	\$	527.80	\$	527.80
40	Front Knuckle Arm LH	/ BT	1	\$	424.80	\$	424.80
41	Front Wheel Bearing LH	/ Jammed	1	\$	382.20	\$	382.20
42	Front Support Panel	X nn	1	\$	381.60	\$	381.60
43	Aircon Condenser	X nn	1	\$	654.90	\$	654.90
44	Radiator Assembly	X nn	1	\$	915.80	\$	915.80
45	Radiator Shroud	X nn	1	\$	108.80	\$	108.80
46	Fan Blade	X nn	1	\$	55.50	\$	55.50
47	Fan Motor Assembly	X nn	1	\$	282.00	\$	282.00
				Parts Sub Total :		\$	14,694.30
				20% Discount		\$	2,938.86
				PARTS TOTAL :		\$	11,755.44

4826.10
-20%
3860.88

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	X nn	1	\$ 50.00
2	Front Bumper Clips - Set	/ MR	1	\$ 50.00
3	Front Headlamp Clips - Set	X nn	1	\$ 50.00
4	Front Grille Assembly Clips - Set	/ MR	1	\$ 50.00
5	Front Support Panel Top Garnish Clips - Set	X nn	1	\$ 50.00
6	Front Fender Inner Cowling Clips - Set	/ MR	1	\$ 50.00
7	Front Bonnet Sealant	X nn	1	\$ 150.00
8	Front Fender LH Sealant	X nn	1	\$ 150.00
9	Front Support Panel Sealant	X nn	1	\$ 150.00
10	Front Door LH Sealant	X nn	1	\$ 150.00
11	Front Wheel Rim LH	/ CUT	1	\$ 1,500.00
12	Front Tyre LH	X nn	1	\$ 450.00
13	Front Bumper Lower Spoiler - Aftermarket	/ MR	1	\$ 1,200.00
14	Radiator Coolant	X nn	1	\$ 50.00
SPECIAL NETT TOTAL :				\$ 4,100.00

1570

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 400 1,600.00
2	To Spray Paint Affected Areas	\$ 600 1,400.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Front Door LH Mechanism	\$ X 150.00
5	To Remove & Refix Aircon Condenser & Top up Gas	\$ X 150.00
6	To Remove & Refix Radiator & Pressure Test	\$ X 150.00
7	To Remove & Refix Front Undercarriage	\$ 100 450.00
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ 80 150.00
9	To Conduct Four Wheel Alignment	\$ 30 150.00
10	To apply anti rust on affected parts	\$ 30 100.00
11	To Conduct Water Leak Test	\$ X 100.00
12	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 4,980.00

1260

Steve (LKK)
7/11/24, 10.30 am
m ll
L/S
L AL Ry
5 days

PARTS TOTAL : \$ 11,755.44
SPECIAL NETT TOTAL : \$ 4,100.00
LABOUR TOTAL : \$ 4,980.00
GRAND TOTAL : \$ 20,835.44

6690.88

L/S - 5352.70
= 5350

LKK Auto Cons. to be notified
the Repairer of the following:

- To resurvey before later repair/repainting
- To display damaged part(s) during the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: