

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0839/2024/KS
DATE : 6-Nov-24
WIP : 37327

4 days

\$ 10423.44

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS KHAW HONG LAN
ADDRESS : BLK 683 TAMPINES STREET 83
#08-478
SINGAPORE 520863

TELEPHONE : HP +65 96411042
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100280372-12
VEHICLE NO : SKD 3720 J
MODEL CODE : AUDI A4 1.8T FSI MU
MODEL YEAR : 24/11/2011
ENGINE NO : CDH 148510
CHASSIS NO : WAUZZZ8K9CA059440
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Nov-24
PLACE OF ACCIDENT : BEDOK NORTH ST1 (BESIDE BLK 216 BEDOK SOUTH ST 1
MARKET & FOOD CENTRE)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKD 3720 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, AND OUTSIDE TEMPERATURE SENSOR.	S/N \$	280.00	/
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE. 350 x 1	S/N \$	700.00	350
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$ 5,372.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 3720 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / BR	1	\$	3,061.00 / 2448.80
2	FRONT BUMPER FIXING PARTS X nn	1	\$	286.00
3	FRONT BUMPER GUIDE SECTION - LH / RH ? x nn	2	\$	112.00
4	FRONT BUMPER SEALING STRIP X nn	1	\$	28.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	1	\$ nn	221.00
6	FRONT VENT GRILLE - LH / RH X nn	2	\$	432.00
7	FRONT FOAM FILLER PIECE ? x nn	1	\$	156.00 / 124.4
8	FRONT BUMPER REINFORCEMENT BEAM ? x nn	1	\$	1,129.00
9	FRONT BUMPER BRACKET TOWING BRACKET - LH / RH ?	2	\$ x nn	574.00
10	FRONT BUMPER SUPPORT - LH / RH ? x nn	2	\$	236.00
11	FRONT BUMPER TOP COVER / BR	1	\$	123.00 / 98
12	RADIATOR GRILLE / BR	1	\$	870.00 / 696
13	RADIATOR GRILLE STRIKER PLATE ? x nn	1	\$	94.00
14	"CAUTION" STICKER / REC	1	\$	25.00 / 19.44
15	HALOGEN HEADLIGHT LH / RH / CUT	-2 1	\$	2,650.00 1060 /
16	HALOGEN HEADLIGHT BRACKET - LH / RH ? x nn	2	\$	196.00
17	HEADLIGHT MOUNTING - LH / RH ? x nn	2	\$	294.00
18	HALOGEN FOG LAMP - LH / RH ? x nn	2	\$	716.00
19	BONNET / BR	1	\$	3,459.00 / 2767.2
20	BONNET ATTACHMENT PARTS X nn	1	\$	184.00
SUB TOTAL SPARE PARTS		:	\$	14,846.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKD 3720 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET HINGE - LH / RH ✓ nn	2	\$ 182.00	
22	BONNET CATCH HOOK X nn	1	\$ 174.00	
23	BONNET LID LOCK WITH MICRO SWITCH X nn	1	\$ 246.00	
24	BONNET BUNGS X nn	4	\$ 28.00	
25	FRONT NO PLATE / M	S/N	\$ 60.00	/
26	SUNDRIESS 1 x nn		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 16,036.00	
TOTAL LABOUR CHARGES		:	\$ 5,372.00	
GRAND TOTAL		:	\$ 21,408.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0839/2024/KS 29-Nov-24 GLORY 1 of 1 SKD 3720 J AUDI A4 1.8T FSI MU	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	FRONT BUMPER TOP COVER / BR		\$ 160.00	127.6
	GRAND TOTAL		\$ 160.00	

For Premium Automobiles Pte Ltd

Steve (LKK)
29/11/24
Resurvey

Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve CLK
8/11/74, 3.7ml
00- ALI AL
EXCESS - ?

PIP, by BCL sy, 4 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT