



# DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

## QUOTATION

DATE: 06/11/2024

REF: SD0B24B60001

VEHICLE NO: SLN5414R

MAKE: HONDA

MODEL: SHUTTLE

PREPARED BY: XIANG

### QUOTATION FOR

NAME: China Taiping Insurance (Singapore) Pte. Ltd

COMPANY NAME: China Taiping Insurance (Singapore) Pte. Ltd

STREET ADDRESS: 3 Anson Road, #16-00 Springleaf Tower

POSTAL CODE: Singapore 079909

PHONE: 6389 6111

ster (LKK)  
7/11/24, 12:00pm  
m n  
1 day  
P/P  
m BCL sm

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
<b>LABOUR</b>							
1	TO REPLACE DOOR MIRROR ASSY RH	1		\$120.00	\$ 120.00		\$ 80 120.00
2	TO SPRAY DOOR MIRROR COVER RH	1		\$100.00	\$ 100.00		\$ 80 100.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	nn 1		\$100.00	\$ 100.00		\$ 100.00
<b>PARTS</b>							
1	DOOR MIRROR ASSY RH x R	1		\$773.20	\$ 773.20		\$ 773.20
SUBTOTAL					\$ 1,093.20	SUBTOTAL	\$ 1,093.20
GST 9%					\$ 98.39	GST 9%	\$ 98.39
TOTAL					\$ 1,191.59	TOTAL	\$ 1,191.59

### REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party assessment on "no prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



(AUTHORISED SIGNATURE)