

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Authorized
meras
8/11/24
1/4 = 2200 /
5 days
to be paid. Harry

VEHICLE NUMBER: GBH2989T

MAKE & MODEL: ISUZU NHR87AUE4AA

FRONT WINDSCREEN RUBBER	neu	\$231.00	✓
FRONT HEADLAMPS L/R X2	^^	\$986.00	X
FRONT HEADLAMPS LOWER SEAL L/R X2	^^	\$64.20	X
FRONT SIDE LAMPS L/R X2	^^	\$342.00	X
FRONT PANEL	1713214	\$655.00	✓
FRONT PANEL LOGO	neu	\$156.00	✓
FRONT PANEL NH STICKER	neu 141V	\$54.00	X
FRONT CORNER PANEL L/R X2	^^	\$658.00	X
FRONT MIRROR STAY LH	^^	\$296.00	X
FRONT MIRROR ROUND LH	^^	\$91.00	X
FRONT MIRROR STAY RH	^^	\$285.00	X
FRONT MIRROR RH	^^	\$168.00	X
FRONT GRILLE	neu	\$612.00	✓
FRONT BUMPER	^^	\$574.00	X
FRONT BUMPER BRACKET L/R X2	^^	\$330.00	X
FRONT BUMPER FOG LAMP COVER L/R X2	^^	\$142.00	X
AIRCON BLOWER ASSY	^^	\$457.00	X
HEATER UNIT	^^	\$1,981.00	X
		\$8,082.20	
	Less 15%	\$1,212.33	
		\$6,869.87	

FRONT PANEL SEALANT	^^	\$80.00	X
FRONT PANEL COMPANY STICKER	neu 141V	\$400.00	X
FRONT GRILLE CLIPS	^^	\$40.00	X
FRONT NUMBER PLATE	^^	\$700.00	X
		<u>\$1,220.00</u>	

TO REMOVE & REFIT FRONT WINDSCREEN	\$150.00	100
TO CHECK FRONT WIRING & HEADLAMP LEVELING	\$60.00	20
TO REMOVE & REFIT DASHBOARD ASSY TO FACILITATE REPAIR	\$350.00	200
TO REPLACE AIRCON BLOWER AND HEATER UNIT, RECHARGE A/C GAS	\$180.00	100

TO PROVIDE LABOUR, WORKMANSHIP	\$1,400.00	600
TO SPRAY PAINT ON AFFECTED PANELS	\$1,000.00	320
RUST PROOFING	\$200.00	30
	<u>\$3,340.00</u>	

Total

\$11,429.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-1646
152
1399.10
1370
2769.10
222
2215