



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 (S737869)

HP: 98888885

Estimation

Date: 16/12/2024

Vehicle: SNN7621Y

Make / Model: TOYOTA VOXY

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / Deep Cut	1	\$ 1,025.00	\$ 1,025.00
2	REAR BUMPER SIDE RETAINER RH x nn	1	\$ 159.00	\$ 159.00
3	REAR BUMPER REFLECTOR COVER RH x nn	1	\$ 160.00	\$ 160.00
				\$ 1,344.00
			Less 25%	\$ 336.00
			Total	\$ 1,008.00
S/Nett items:				
1	REAR REVERSE SENSOR x nn	1 SET	\$ 250.00	\$ 250.00
2	REAR BUMPER CLIP / Nec	1 SET	\$ 80.00	\$ 80.00
				\$ 330.00
Labour to: REAR				
1	TO CHECK ELECTRICAL WIRING	1	\$ 100.00	\$ 100.00
2	TO REMOVE AND REFIT REVERSE SENSOR/CAMERA	1	\$ 150.00	\$ 150.00
3	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00
4	PANEL BEATING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00
				\$ 1,050.00
Parts Replacement Amount				\$ 1,338.00
Total Amount for Labour				\$ 1,050.00
Total Amount				\$ 2,388.00

Steve (LKK)
17/12/24, 5.00pm
Without Prejudice
P/P
Resurvey Before Spray
2 days