

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP INC.
Veron

TAN KATHERINE
BLK 519B TAMPINES CENTRAL 8 #08-29
SINGAPORE 522519

TAX INVOICE

Repair Code : CLM18449

Date in : 05/11/2024

Vehicle Num. : SKZ3019K

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104542742/1ZRY238130

Contact : 97381654

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehd</i>	1	905.40	905.40 765
FRONT BUMPER LOWER GRILLE <i>Int</i>	1	237.60	237.60 ✓
FRONT BUMPER REINFORCEMENT <i>Reided</i>	1	615.60	615.60 545
FRONT BUMPER RH FOGLAMP <i>Canled</i>	1	469.00	469.00 390
FRONT BUMPER RH FOGLAMP GARNISH <i>lt</i>	1	168.10	168.10 ✓
FRONT BUMPER SIDE RETAINER L/R <i>no RH dngd</i>	2	130.80	261.60 130.80
FRONT BUMPER SPONGE <i>Canled</i>	1	124.50	124.50 ✓
FRONT BUMPER UNDER COVER <i>no Rehd</i>	1	531.40	531.40 385
FRONT GRILLE <i>lt</i>	1	1337.20	1337.20 895
FRONT GRILLE 'LOGO' EMBLEM <i>no</i>	1	85.60	85.60 ✓ 98.17
FRONT HEADLAMP (LED) L/R <i>Rit canled, Lt</i>	2	4617.30	9234.60 3950
FRONT RH FENDER <i>no</i>	1	1386.90	1,386.90 +
FRONT RH FENDER 'VVT-I' EMBLEM <i>no</i>	1	49.30	49.30 +
FRONT RH FENDER INNER SHIELD <i>no torn</i>	1	351.50	351.50 +
FRONT WASHER TANK <i>Rehd</i>	1	303.30	303.30 125
FRONT WASHER TANK MOTOR <i>no</i>	1	405.80	405.80 +

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN KATHERINE
BLK 519B TAMPINES CENTRAL 8 #08-29
SINGAPORE 522519

Contact : 97381654

TAX INVOICE

Repair Code : CLM18449
Date in : 05/11/2024
Vehicle Num. : SKZ3019K
Model : TOYOTA COROLLA ALTIS 1.6L CVT
Chassis/Eng# : MR053REH104542742/1ZRY238130

	Subtotal before discount	7801.60	16,467.40
Percentage discount 25%			4,116.85
	Sub-total 1	5851.20	12,350.55
FRONT BUMPER CLIPS - SET <i>per</i>	1	80.00	80.00 <i>30</i>
FRONT BUMPER NUMBER PLATE	1	25.00	25.00 <i>+</i>
FRONT BUMPER NUMBER PLATE HOLDER <i>3 per</i>	1	50.00	50.00 <i>+</i>
FRONT BUMPER PARKING SENSOR - SET <i>per and</i>	1	280.00	280.00 <i>200</i>
FRONT GRILLE CLIPS - SET <i>per</i>	1	30.00	30.00 <i>-</i>
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>per</i>	1	50.00	50.00 <i>+</i>
	Subtotal before discount		515.00
Percentage discount 0%			0.00
	Sub-total 2		515.00
	Parts-total		12,865.55

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

LKK Auto Consultants henceforth the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

Acknowledged by Repairer
Signature
Date

page 2

Labour Total

1,930.00

Parts & Labour Total

14,795.55

Adm
L/S 07/11/24

5.31C

total: 6641.20
L/S: 5.31C