

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

INSURANCE:

First Capital

DATE: 25-Jun-24

Model: SHA 7938 Z

Vehicle No.: TOYOTA PRIUS (NEW)

Description	Qty	List Price	Amount
FRONT BUMPER broken	1	\$ 855.60	\$ 855.60
FRONT BUMPER SPONGE tan	1	\$ 158.00	\$ 158.00
FRONT BUMPER REINFORCEMENT Replaced	1	\$ 713.60	\$ 713.60
FRONT BUMPER RETAINER src	2	\$ 76.80	\$ 153.60
FRONT BUMPER LOWER GARNISH broken	1	\$ 385.50	\$ 385.50
FRONT BUMPER LOWER COVER broken	1	\$ 168.00	\$ 168.00
FRONT BUMPER TOW COVER Replaced o/s	1	\$ 24.60	\$ 24.60
FRONT BUMPER SENSOR Dam	2	\$ 380.00	\$ 760.00
FRONT BUMPER SENSOR WIRE src	1	\$ 289.60	\$ 289.60
FRONT BUMPER EMBLEM Hec	1	\$ 1,103.70	\$ 1,103.70
FRONT BUMPER TOP GRILLER broken	1	\$ 253.00	\$ 253.00
FRONT BUMPER GRILLER INNER BASE HH	1	\$ 159.20	\$ 159.20
FRONT BUMPER GRILLER OUTER GARNISH distorted	1	\$ 342.60	\$ 342.60
FRONT RADAR SENSOR Dam	1	\$ 4,680.50	\$ 4,680.50
FRONT BRACE PANEL St	1	\$ 155.20	\$ 155.20
FRONT TOP PANEL Replaced	1	\$ 586.60	\$ 586.60
FRONT LOWER SUPPORT PANEL sign	1	\$ 524.90	\$ 524.90
FRONT BUMPER TOP RUBBER HH	1	\$ 185.50	\$ 185.50
HEAD LAMP PANEL Replaced	2	\$ 200.30	\$ 400.60
HEAD LAMP SIDE PANEL Replaced	2	\$ 332.80	\$ 665.60
FRONT TOP PANEL GARNISH HH	1	\$ 316.40	\$ 316.40
HEAD LAMP broken	2	\$ 5,556.70	\$ 11,113.40
RADIATOR ASSY St	1	\$ 3,120.50	\$ 3,120.50
RADIATOR FAN MOTOR HH	1	\$ 752.30	\$ 752.30
RADIATOR FAN COWLING broken	1	\$ 404.20	\$ 404.20
RADIATOR FAN BLADE distorted	1	\$ 232.20	\$ 232.20
AIR-CON CONDESER St	1	\$ 2,416.00	\$ 2,416.00
AIR-CON FAN MOTOR HH	1	\$ 752.30	\$ 752.30
AIR-CON FAN BLADE distorted	1	\$ 298.00	\$ 298.00
HORN HH	2	\$ 157.80	\$ 315.60

✓
✓
✓
X
✓
✓
✓
✓
X
✓
X
✓
✓
X
✓
✓
X
X
✓
✓
X
✓
✓
X
✓
✓
X
✓
X

[illegible]

