

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

LKK

Name : Lau Chin Kok (97786750)

Accident Date : 12-Oct-24

Vehicle No : JNW7708 (DOR: 11102012)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	\$ 11 640.00 X
1	Fork under bracket	\$ 11 225.00 X
1	Front wheel rim	\$ 11 495.00 X
1	Front rim shaft	\$ 11 105.00 X
1	Front rim bearing	\$ 11 88.00 X
1	Front brake disc	\$ 11 185.00 X
1	Handle bar	\$ 8u 145.00 X
1	Handle-bar ends (1 set)	\$ 11 125.00 X
1	Hand grip (1 set)	\$ 11 90.00 X
1	Handle bar inner bracket	\$ 11 135.00 X
1	Rear exhaust pipe	\$ 11 485.00
1	Side mirrors (1 set)	\$ 11 110.00
1	Front signals (1 set)	\$ 11 140.00 X
1	Fairing assy (1 set)	\$ 11 650.00
1	Front footrest bracket	\$ 11 65.00
2	Front footrest rubbers	\$ 11 70.00
1	Brake pedal	\$ 11 165.00
1	Rear footrest: 015	\$ 11 80.00
1	Rear exhaust chrome	\$ 11 156.00
		\$ 4,154.00
	Less 10%	\$ 415.40
		\$ 3,738.60

Special Net Items

1	Number plate (1 set)	\$ 11 38.00 10
2	Fork oils	\$ 11 30.00 X
2	Fork oil seals	\$ 11 56.00 X
1	Steering cone (1 set)	\$ 11 185.00 X
1	Rear box	\$ 11 480.00 250
1	Rear box bracket	\$ 11 180.00 X
1	Sticket (1 set)	\$ 11 120.00 60
		\$ 1,089.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Lau Chin Kok (97786750)

Accident Date : 12-Oct-24

Vehicle No : JNW7708 (DOR: 11102012)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD) S\$40.00	refer to LO \$D	- X
2	To check wiring and reset headlamp focusing	\$ 17	80.00 X
3	To provide labour	\$	480.00 300
4	To re-align body frame	\$ 17	420.00 X
		\$	980.00
Grand Total		\$	5,807.60

Singapore Dollars: Five Thousand Eight Hundred Seven and Cents: Sixty only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: