

TSL AUTO PRO SELECTION PTE LTD

TO	: NTUC	DATE	: 12/11/2024
VEHICLE NO	: GBD1223Y (2014)	<i>Hui Rong</i>	
VEHICLE MODEL	: MITSUBISHI CANTER		
CHASSIS NO	: FEA01BA00304		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	TAILLAMP	1	\$ 298.40	\$ 298.40
2	TAILLAMP PANEL	1	\$ 149.50	\$ 149.50
TOTAL PRICE:				\$ 447.90
LESS 25%				\$ 111.97
SUB TOTAL PRICE:				\$ 335.93

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR REFRIGERATOR STAINLESS STEEL PILLAR <i>Dented</i>	1	\$ 1,500.00	\$ 1,500.00
2	REAR REFRIGERATOR SIDE PANEL <i>Torn</i>	1	\$ 3,500.00	\$ 3,500.00
3	REAR REFRIGERATOR SIDE PANEL ADVERTISEMENT STICKER	1	\$ 2,000.00	\$ 2,000.00
TOTAL:				\$ 7,000.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 500.00	<i>X</i>	
3	WIRING CHECK	\$ 50.00	<i>X 30</i>	
TOTAL		\$ 1,550.00	<i>830</i>	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,335.93

TOTAL LABOUR COST: \$ 1,550.00

TOTAL REPAIR COST: \$ 8,885.93

total 6280

L/S: SK

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SK