

ADVANCE AUTO GARAGE

TO	: CHINA TAIPING	08/11/24
VEHICLE NO	: SKK3006B (2019)	
VEHICLE MODEL	: MERCEDES BENZ AMG C63S	
CHASSIS NO	: WDD2053872F854057	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Deland</i>	1	\$ 2,445.00	\$ 2,445.00
2	REAR BUMPER SIDE HOLDER <i>cracked</i>	1	\$ 149.00	\$ 149.00
3	REAR BUMPER SIDE GARNISH <i>crack</i>	1	\$ 195.00	\$ 195.00
4	REAR BUMPER SENSOR <i>Not new</i>	1	\$ 285.00	\$ 285.00
5	TAILLAMP <i>cracked</i>	1	\$ 1,045.00	\$ 1,045.00
6	TAILLAMP LOWER BRACKET <i>new</i>	1	\$ 89.00	\$ 89.00

TOTAL PRICE: \$ 4,208.00
 LESS 10% \$ 420.80
 SJB TOTAL PRICE: \$ 3,787.20

3834

3450.60

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2	REAR BUMPER STICKER WRAP <i>new</i>	1	\$ 500.00	\$ 500.00

TOTAL: \$ 550.00

350

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	200	
3	WIRING CHECK	\$ 50.00	30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
5	TO PERFORM DIAGNOSTIC TEST	\$ 250.00	125	

TOTAL: \$ 1,200.00

480

ESTIMATE REPORT

TOTAL PARTS COST: \$ 4,337.20
 TOTAL LABOUR COST: \$ 1,200.00
 TOTAL REPAIR COST: \$ 5,537.20

total 4280.60

1/s: 3.4K

03Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.4K
3 days