

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : WONG CHONG MENG  
36 MARSILING DRIVE  
#05-411  
SINGAPORE 730036  
TEL: 96748096  
ATTN:

Estimate No: MC1904407  
Date: 27 Jun 2024  
Policy No: P10856574R01  
Veh Reg No: SLW8727X  
Make/Model: MITSUBISHI ATTRAGE  
1.2 CVT

Your Ref No: SLW8727X  
Claim Type: Third Party → *mandet*  
Accident Date: 26/06/2024  
TP Veh Reg No: 20364MID

*Not Notified*  
*11pm @ 1800h*  
*Resurvey After Paint*  
*5 days*

## Estimate Repair Cost to Vehicle No :SLW8727X

Description	Quantity	List Price	Amount
		S\$	S\$
<b>SPARE PARTS</b>			
1 REAR WINDSCREEN MLDG W GLASS	1 PC	<i>nn</i> 514.00	X
2 REAR FENDER RH	1 PC	<i>nn</i> 723.00	✓
3 REAR FENDER COWLING RH	1 PC	<i>nn</i> 38.00	X
4 REAR FENDER COWLING CLIPS	8 PC	<i>nn</i> 48.00	X
5 REAR BUMPER	1 PC	708.00	7
6 REAR BUMPER SIDE RETAINER RH	1 PC	<i>nn</i> 26.00	X
7 REAR BUMPER CLIPS	15 PC	<i>nn</i> 90.00	✓
8 REAR DOOR RH	1 PC	<i>nn</i> 1,009.00	X
9 REAR DOOR INNER LOCK	1 PC	<i>nn</i> 290.00	X
10 REAR DOOR TAPE	1 PC	<i>nn</i> 27.00	X
		3,473.00	
		Less 10%	347.30
			3,125.70
<b>LABOUR</b>			
11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>15/</i>
12 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	<i>nn</i> 80.00	X
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
14 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	<i>nn</i> 80.00	X
15 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	150.00	<i>100/</i>
16 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	<i>nn</i> 60.00	X
17 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>30/</i>
18 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	<i>650/</i>
19 TO SPRAY REAR BUMPER,REAR FENDER RH,REAR DOOR RH	1 PC	800.00	<i>600/</i>
		2,190.00	2,190.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

