

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6515 6888 / 9847 8613 (HELPLINE)
EMAIL : enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg



Not Authorized
11 Sep 8
Recovery After Paint
9 days

QUOTATION

M/S : SIAH TEONG BOON

BLK 963 BUKIT TIMAH ROAD #06-22
SINGAPORE 589656

H/P: 94516683

NO: WQT0801486
DATE: 02 Nov 2024
A/C CODE: C021150

YOUR REF: SJU1128E
VEH REG NO: SJU1128E
MAKE/MODEL: TOYOTA LEXUS IS250
SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		S\$		S\$

WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE.

DOA: 01/11/2024 @1620 HRS

ACCIDENT INVOLVING: SJU1128E & SMH75M

CLAIM TYPE: 3RD PARTY CLAIM AGAINST SMH75M (INSURED WITH CHINA TAIPING INSURANCE (S) PTE LTD)

1	REAR BUMPER	1 PC	1,563.30	<i>Dis/cm</i> 1,563.30	✓
2	REAR BUMPER REFLECTOR RH	1 PC	175.90	<i>sa</i> 175.90	X
3	REAR BUMPER SIDE RETAINER NO. 1	1 PC	96.90	<i>cm</i> 96.90	—
4	REAR BUMPER SIDE RETAINER NO. 2	1 PC	130.50	<i>cm</i> 130.50	—
5	REAR RH AIR DUCT	1 PC	74.30	<i>Dis</i> 74.30	—
6	REAR BUMPER LOWER EXTENSION	1 PC	96.90	<i>R</i> 96.90	R
7	REAR COMBINATION LAMP RH	1 PC	1,075.40	<i>sa</i> 1,075.40	X
8	REAR LAMP ASSY RH	1 PC	815.00	<i>sa</i> 815.00	X
9	BOOT LID	1 PC	1,547.10	<i>R</i> 1,547.10	X
10	BOOT LID LOGO	1 PC	125.00	<i>na</i> 125.00	X
11	BOOT LID EMBLEM - LEXUS	1 PC	85.00	<i>na</i> 85.00	X
12	BOOT LID EMABLE - IS250	1 PC	90.00	<i>na</i> 90.00	A
13	BOOT LID HINGES LH & RH	2 PC	98.00	<i>R</i> 196.00	X
14	BACK WEATHERSTRIP	1 PC	293.60	<i>sa</i> 293.60	X
15	COVER, SIDE OPENING, BOOT LID RH	1 PC	48.00	<i>sa</i> 48.00	X
16	REAR FENDER RH <i>2018.40</i>	1 PC	2,181.20	<i>R</i> 2,181.20	✓
17	REAR FENDER SHIELD RH	1 PC	329.30	<i>Return</i> 329.30	✓
18	REAR FENDER STONE DEFLECTOR STICKER	1 PC	50.00	<i>na</i> 50.00	—
19	REAR DOOR RH <i>2602.80</i>	1 PC	2,918.20	<i>R</i> 2,918.20	✓
20	REAR DOOR LOCK RH	1 PC	801.70	<i>na</i> 801.70	—
21	REAR DOOR LOCK CATCHER RH	1 PC	63.40	<i>Dis</i> 63.40	—
22	REAR DOOR WINDOW REGULATOR MOTOR	1 PC	2,200.40	<i>sa</i> 2,200.40	X
23	REAR DOOR WINDOW REGULATOR	1 PC	312.60	<i>sa</i> 312.60	X
24	REAR DOOR OUTER HANDLE RH	1 PC	120.50	<i>Dis</i> 120.50	✓
25	REAR DOOR OUTER HANDLE COVER RH	1 PC	44.30	<i>Replaced</i> 44.30	X
26	REAR DOOR INNER DOOR BOARD RH <i>1812.60</i>	1 PC	3,220.30	<i>Dis/cm</i> 3,220.30	✓

109

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6515 6888 / 9847 8613 (HELPLINE)
EMAIL: enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg



QUOTATION

M/S : SIAH TEONG BOON

NO:

WQT0801486

DATE:

02 Nov 2024

PAGE:2

Description	Quantity	Unit Price	%	Amount
		S\$		S\$

WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE.

DOA: 01/11/2024 @1620 HRS

ACCIDENT INVOLVING: SJU1128E & SMH75M

CLAIM TYPE: 3RD PARTY CLAIM AGAINST SMH75M (INSURED WITH CHINA TAIPING INSURANCE (S) PTE LTD)

27	REAR DOOR WEATHERSTRIP RH	1 PC	385.20	385.20	X
28	REAR DOOR HINGE UPPER RH	1 PC	137.10	137.10	✓
29	REAR DOOR HINGE LOWER RH	1 PC	120.30	120.30	✓
30	REAR DOOR CHECK RH	1 PC	319.60	319.60	X
31	REAR DOOR WEATHERSTRIP QUARTER WINDOW RH	1 PC	98.00	98.00	X
32	REAR DOOR FRAME GARNISH RH	1 PC	255.00	255.00	X
33	REAR DOOR TAPE RH	1 PC	35.00	35.00	✓
34	COVER, REAR DOOR SERVICE HOLE RH	1 PC	38.00	38.00	X
35	RH SIDE SKIRT	1 PC	1,089.40	1,089.40	✓
36	REAR BUMPER CLIPS	10 PC	4.00	40.00	✓
37	REAR FENDER SHIELD CLIPS	10 PC	5.00	50.00	✓
38	SIDE SKIRT CLIPS	8 PC	5.00	40.00	✓
39	BACK WINDSCREEN MOULDING	1 PC	120.00	120.00	✓
40	AXLE OIL	2 LTS	15.00	30.00	X
41	REAR RH 17" SPORT RIM (G) 2820.90	1 PC	3,220.00	3,220.00	✓
42	REAR RH TYRE - 245/45/17 MICHELIN PS5	1 PC	280.00	280.00	✓
43	REAR STABILIZER BUSH	2 PC	45.00	90.00	X
44	REAR STABILIZER LINK RH	1 PC	140.00	140.00	✓
45	REAR UPPER CONTROL ARM NO. 1 RH	1 PC	450.00	450.00	✓
46	REAR UPPER CONTROL ARM NO. 2 RH	1 PC	250.00	250.00	✓
47	REAR SUSPENSION ARM NO.1 RH	1 PC	260.00	260.00	✓
48	REAR SUSPENSION ARM NO. 2 RH	1 PC	260.00	260.00	✓
49	LINK ASSY, TOE CONTROL RH	1 PC	155.00	155.00	✓
50	CARRIER SUB ASSY, REAR AXLE RH	1 PC	650.00	650.00	✓
51	REAR SHOCK ABSORBER RH	1 PC	580.00	580.00	✓
52	SUPPORT ASSY, REAR SUSPENSION RH	1 PC	250.00	250.00	✓
53	BUMPER, REAR SPRING NO. 1 RH	1 PC	50.00	50.00	X
54	INSULATOR, REAR COIL SPRING UPPER RH	1 PC	45.00	45.00	X
55	INSULATOR, REAR COIL SPRING LOWER RH	1 PC	45.00	45.00	X
56	SUPPLY BACK WINDSCREEN SEALTANT	1 SVC	40.00	40.00	✓
57	TO REMOVE BACK WINDSCREEN TO ENABLE TO REPLACE REAR FENDER & FIX SAME.	1 SVC	120.00	120.00	✓

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6515 6888 / 9847 8613 (HELPLINE)
EMAIL : enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg

**QUOTATION****M/S : SIAH TEONG BOON****NO: WQT0801486**
DATE: 02 Nov 2024

PAGE:3

Description	Quantity	Unit Price	%	Amount
		S\$		S\$
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE. DOA: 01/11/2024 @1620 HRS ACCIDENT INVOLVING: SJU1128E & SMH75M CLAIM TYPE: 3RD PARTY CLAIM AGAINST SMH75M (INSURED WITH CHINA TAIPING INSURANCE (S) PTE LTD)				
58 TO REMOVE & REPLACE UNDERCARRIAGE PARTS	1 SVC	350.00		350.00 2cd
59 COMPUTERIZE WHEEL ALIGNMENT	1 SVC	80.00		80.00 ✓
60 TO REMOVE & REPLACE TYRE, RIM & BALANCING.	1 SVC	50.00		50.00 2cd
61 TO TRANSFER REAR DOOR MECHNISM & CHECK FUNCTION.	1 SVC	80.00		80.00 6cd 1200 ✓
62 TO CUT, WELD & STRAIGHTEN RH PORTION CAUSED BY ACCIDENT, ADJUST & REPLACE DAMAGE PARTS.	1 SVC	1,800.00		1,800.00 9cd 1100 ✓
63 TO TUFF COAT REPAIRED AREAS.	1 SVC	80.00		80.00 6cd
64 TO SPRAY PAINT ON REPAIRED AREAS	1 SVC	1,700.00		1,700.00 13cd 1100 ✓
Total				S\$ 32,437.40
Add GST @ 9%				2,919.37
Grand Total				S\$ 35,356.77

TOTAL: SINGAPORE DOLLAR THIRTY FIVE THOUSAND THREE HUNDRED FIFTY SIX AND CENTS SEVENTY SEVEN ONLY

SIAH TEONG BOON**For RICARDO AUTO CENTRE PTE LTD**

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6515 6888 / 9347 8613(HELPLINE)
EMAIL: enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg

**QUOTATION****M/S : SIAH TEONG BOON**

BLK 963 BUKIT TIMAH ROAD #06-22
SINGAPORE 589656

H/P: 94516683**NO: WQT0801558****DATE: 13 Jan 2025****A/C CODE: C021150****YOUR REF: SJU1128E****VEH REG NO: SJU1128E****MAKE/MODEL: TOYOTA LEXUS IS250****SALESMAN:**

PAGE:1

Description	Quantity	Unit Price	%	Amount
		<u>S\$</u>		<u>S\$</u>

WE SUBMIT HERewith OUR SUPPLEMENTARY ITEMS TO ABOVE MENTIONED VEHICLE.

DOA: 01/11/2024 @ 1620 HRS

ACCIDENT INVOLVING: SJU1128E & SMH75M

CLAIM TYPE: 3RD PARTY CLAIM AGAINST SMH75M (INSURED WITH CHINA TAIPING INSURANCE)

1	WIRE SKID CONTROL	1 PC	140.00	<i>B</i> 140.00 ✓
2	REAR RH ABS WHEEL SPEED SENSOR	1 PC	330.00	<i>share</i> 330.00 ✓
3	COVER HANDLE FD/RH	1 PC	44.00	<i>RM</i> 44.00 ✓
4	ROCKER PANEL SHIELD REAR RH	1 PC	68.00	<i>CM</i> 68.00 ✓
5	REAR BUMPER CORNER BRACKET RH	1 PC	32.00	<i>CM</i> 32.00 ✓
6	REAR BUMPER SPONGE	1 PC	125.00	<i>RM</i> 125.00 X
7	FRAME ASSY, HANDLE OUTSIDE REAR DOOR RH	1 PC	172.00	<i>DIY</i> 172.00 ✓
8	REAR BUMPER REINFORCEMENT	<i>Red</i> 1 PC <i>RM</i>	514.00	514.00 X
9	BOOT LID LOCK	1 PC	570.00	<i>R</i> 570.00 X

Total S\$ 1,995.00

Add GST @ 9% 179.55

Grand Total S\$ 2,174.55

TOTAL: SINGAPORE DOLLAR TWO THOUSAND ONE HUNDRED SEVENTY FOUR AND CENTS FIFTY FIVE ONLY

SIAH TEONG BOON**For RICARDO AUTO CENTRE PTE LTD**

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE