

ASS. REC. BY:

Tajm

REF:

CD/FC124110147/Tm93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$115K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seer: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF1455 Yr Regn: 2023, 06

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen C5 c.c. 1199

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 5798 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VR7AR4N55N L05 9053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRM / STD A/Rim or

Tyre Size: F: 235/55R16

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 10/1/25

Survey held at C&C Pardon Gdn

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / B-structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

ESTIMATE

Invoice Name & Address			Owner Name & Vehicle Info		
Ko Tuck Chong Willy			/Ko Tuck Chong Willy		
46 LENGKONG TUJOH			Reg No/Reg Date SLF1455 / 30/06/2023		
#02-25			Date In/Mileage / 0		
VACANZA @ EAST			Chassis No VR7ARHNSSNL059053		
Singapore 417396			Engine No 10XVD71979263		
Contact No Mobile: 98175037			Make/Model CIT/C5 AIRCROSS 1.2 ML FEEL PLUS		
			Colour/Trim F4M / V4F PVC NIXON V249+		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00077	Cash	05/11/2024/ 10:50	TLL	1210/ Lim Teng Keat	10524

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT				
TP CLAIM MS 1ST				
DOA 09/10/2024				
SUR				
00 REPAIR DAYS				
E PNT88000				1520 2280.00
TO REPLACE FRT BUMPER,	760			
REPAIR FRT LHS FENDER, AND ACCIDENT AFFECTED AREA				
E PNT98000				1100 1650.00
PAINT WORK ON FRT BUMPER, FRT LHS FENDER	550			
E PNT88000				120 240.00
TO REMOVE & REFIT FRT PARKING SENSOR				
A 54900099				150 180.00
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				
A 10028901				380.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				
M SUNDRY				40 80.00
SUNDRIES				
M SUNDRY				X 580.00
TO SUPPLY FRT LHS TYRE 235/55 R18				
M SUNDRY				120.00
TO REPLACE FRT LHS RIM & TYRE INCLUDING BALANCING				
E WHEELALIGNMENT120LB&P				250.00
To Conduct Computerize Full Wheel Alignment				
M PARE-CHOCs, FRONT BUMPER				
M JUPE AV	1.00	1390.00	0.00	? 1390.00
M ENJOLIV PA	1.00	804.00	0.00	X 804.00
M LOT SUPPOR	1.00	196.00	0.00	? 196.00
M WING MOULDING LH AILES AVANT	1.00	169.00	0.00	mc 169.00
M ROUE ALLIA	1.00	344.00	0.00	int 344.00
	1.00	594.00	0.00	int 594.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirm & accepted by

Tanjil 97495749
 10/1/25 e 245

Tanjil C (Kuantan) 5-6 days
 p/p Resurvey new parts

Authorized signatory and company stamp

Parts	
Labour	3,497.00
Standard Menu	4,980.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	0.00
Total(w/o GST)	780.00
	9,257.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.