

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Ko Tuck Chong Willy		Cust No/Name /Ko Tuck Chong Willy	
46 LENGKONG TUJOH		Reg No/Reg Date SLF145S / 30/06/2023	
#02-25		Date In/Mileage / 0	
VACANZA @ EAST		Chassis No VR7ARHNSSL059053	
Singapore 417396		Engine No 10XVD71979263	
Contact No Mobile: 98175037		Make/Model CIT/C5 AIRCROSS 1.2 ML FEEL PLUS	
		Colour/Trim F4M / V4F PVC NIXON V249+	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00077	Cash	05/11/2024/ 10:50	TLL	1210/ Lim Teng Keat	10524

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT				
TP CLAIM MS 1ST				
DOA 09/10/2024				
SUR				
00 REPAIR DAYS				
E PNT88000				2280.00
TO REPLACE FRT BUMPER,				
REPAIR FRT LHS FENDER, AND ACCIDENT AFFECTED AREA				
E PNT98000				1650.00
PAINT WORK ON FRT BUMPER, FRT LHS FENDER				
E PNT88000				240.00
TO REMOVE & REFIT FRT PARKING SENSOR				
A 54900099				180.00
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				
A 10028901				380.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				
M SUNDRY				80.00
SUNDRIES				
M SUNDRY				580.00
TO SUPPLY FRT LHS TYRE 235/55 R18				
M SUNDRY				120.00
TO REPLACE FRT LHS RIM & TYRE INCLUDING BALANCING				
E WHEELALIGNMENT120LB&P				250.00
To Conduct Computerize Full Wheel Alignment				
M PARE-CHOCs, FRONT BUMPER	1.00	1390.00	0.00	1390.00
M JUPE AV	1.00	804.00	0.00	804.00
M ENJOLIV PA	1.00	196.00	0.00	196.00
M LOT SUPPOR	1.00	169.00	0.00	169.00
M WING MOULDING LH AILES AVANT	1.00	344.00	0.00	344.00
M ROUE ALLIA	1.00	594.00	0.00	594.00

Confirm & accepted by

Parts	3,497.00
Labour	4,980.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	780.00
Total(w/o GST)	9,257.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.