

ASS. REC. BY:

REF: TD /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$55K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 11/28

Person Contacted: _____

Vehicle: IN / OUT

Veh No: STM132RYr Regn: 12. 98Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy AllionC.C. 1997Colour: h. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: N8T260 3034520Gen. Cohd: Good / Pair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 195/65R15R: Nexen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 4 mmL/Bal. 9 mmL/Bal. 4 mmD.O.A. 29/10/24D.O.I. 11/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body & o/s frThe UIC / Chassis frame / Body Structure affected due to collision. ☒

Date / Time

Action / Instruction

Bothy Flat, Bonnet jammed, Got BT

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS. SI

F. P. S.

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Repairer Estimates

(Co.Reg.No:201311788Z)

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg; kenneth.ding@dingauto.sg

India International Insurance Pte Ltd (HQ)

Singapore

Claim Type:	THIRD PARTY
Policy No:	
Vehicle Reg. No.:	SJM132R
Party At Fault:	UNKNOWN

Ref. No:
Date of Loss: 29/10/2024
Driveable?

Make/Model:	TOYOTA ALLION, 1.5 (A)
Vehicle Colour:	SILVER
Engine No:	1N2D233930
Odometer:	0 KM

Vehicle Reg. Date: 18/12/2008

Chassis No: NZT2603034520

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Not Withoin
11/24 @ 7/1055?

Present Location: DING AUTO PTE LTD (HQ)

Parts	47,152.60
Miscellaneous Items	492.00
Labour	6,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	54,544.60
+ GST 9.00% (S\$)	4,909.01
Nett Amount (S\$)	59,453.61

This claim is handled by: NURHADY ALIFF FARASYI

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 09 Nov 2024)

Parts: 143

TOYOTA ALLION 1.5 (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SJM132R/09/11/2024 12:29

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	Nil	0.00	0.00	*600.00 F ✓
2	1		*FRONT BUMPER RETAINER LHS	CM	0.00	0.00	*45.00 F ✓
3	1		*FRONT BUMPER RETAINER RHS	CM	0.00	0.00	*45.00 F ✓
4	1		*FRONT BUMPER LOWER GARNISH	Nil	0.00	0.00	*120.00 F ✓
5	1		*FRONT BUMPER LOWER COVER	Nil	0.00	0.00	*125.00 F ✓
6	1		*FRONT BUMPER LOWER GRILLE	Nil	0.00	0.00	*115.00 F ✓
7	1		*FRONT FOGLAMP LHS	Nil	0.00	0.00	*120.00 F ✓
8	1		*FRONT FOGLAMP RHS	Nil	0.00	0.00	*120.00 F ✓
9	1		*FRONT FOGLAMP COVER LHS	Nil	0.00	0.00	*45.00 F ✓
10	1		*FRONT FOGLAMP COVER RHS	Nil	0.00	0.00	*45.00 F ✓
11	1		*FRONT UPPER RAD GRILLE	Nil	0.00	0.00	*220.00 F ✓
12	1		*FRONT RAD GRILLE EMBLEM	Nil	0.00	0.00	*55.00 F ✓
13	1		*FRONT RADIATOR TOP GARNISH	CM	0.00	0.00	*45.00 F ✓
14	1		*FRONT HEADLAMP LHS	Bn	0.00	0.00	*350.00 F ✓
15	1		*FRONT HEADLAMP RHS	m3 CM	0.00	0.00	*350.00 F ✓
16	1		*FRONT BONNET	Bn	0.00	0.00	*550.00 F ✓
17	1		*FRONT BONNET HINGE LHS	Bn	0.00	0.00	*40.00 F ✓
18	1		*FRONT BONNET HINGE RHS	Nil	0.00	0.00	*40.00 F ✓
19	1		*FRONT BONNET INSULATOR		0.00	0.00	*150.00 F ?
20	1		*FRONT BONNET STAY		0.00	0.00	*40.00 F ?
21	1		*FRONT BONNET LOCK	Bn	0.00	0.00	*55.00 F ✓
22	1		*FRONT BONNET CABLE		0.00	0.00	*45.00 F ?
23	1		*FRONT BONNET WEATHERSTRIP	Tn	0.00	0.00	*35.00 F ✓
24	1		*FRONT BUMPER SPONGE	Nil	0.00	0.00	*65.00 F ✓
25	1		*FRONT BUMPER REINFORCEMENT PANEL	Bn	0.00	0.00	*145.00 F ✓
26	1		*FRONT HORN LHS	Bn	0.00	0.00	*55.00 F X
27	1		*FRONT HORN RHS	Bn	0.00	0.00	*55.00 F X
28	1		*FRONT SUPPORT PANEL COMPLETE	Bn	0.00	0.00	*450.00 F ✓
29	1		*FRONT CROSSMEMEBER PANEL LHS	Bn	0.00	0.00	*180.00 F ✓
30	1		*FRONT CROSSMEMEBER PANEL RHS	Bn	0.00	0.00	*180.00 F ✓
31	1		*RADIATOR ASSY		0.00	0.00	*550.00 F ?
32	1		*RADIATOR RESERVE TANK	Nil	0.00	0.00	*100.00 F ✓
33	1		*RADIATOR RESERVE TANK COVER		0.00	0.00	*40.00 F ?
34	1		*RADIATOR RESERVE TANK HOSE		0.00	0.00	*25.00 F ?
35	1		*RADIATOR FAN COWLING		0.00	0.00	*110.00 F ?
36	1		*RADIATOR FAN BLADE		0.00	0.00	*85.00 F ?
37	1		*RADIATOR FAN MOTOR		0.00	0.00	*190.00 F ?
38	1		*RADIATOR FAN COWLING TOP COVER		0.00	0.00	*75.00 F ?
39	1		*CONDENSER		0.00	0.00	*600.00 F ?
40	1		*A/C COMPRESSOR		0.00	0.00	*1,500.00 F ?
41	1		*A/C DISCHARGE PIPE IN		0.00	0.00	*240.00 F ?
42	1		*A/C DISCHARGE PIPE OUT		0.00	0.00	*320.00 F ?
43	1		*AIR INTAKE DUCT		0.00	0.00	*65.00 F ?
44	1		*AIR INTAKE HOSE		0.00	0.00	*65.00 F ?
45	1		*AIR CLEANER BOX		0.00	0.00	*480.00 F ?

Ding Auto Pte Ltd/SJM132R/09/11/2024 12:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*AIR FILTER	0.00	0.00	*25.00 F	7
47	1		*FRONT BRACE PANEL	0.00	0.00	*65.00 F	7
48	1		*WASHER RESERVOIR	0.00	0.00	*90.00 F	7
49	1		*WASHER RESERVOIR FILLER NECK	0.00	0.00	*80.00 F	7
50	1		*WASHER RESERVOIR CAP	0.00	0.00	*30.00 F	7
51	1		*AIR INTAKE MANIFOLD	0.00	0.00	*450.00 F	7
52	1		*MAF SENSOR	0.00	0.00	*250.00 F	7
53	1		*AIR INTAKE MANIFOLD GASKET	0.00	0.00	*58.00 F	7
54	1		*FRONT CHASSIS PANEL LHS	0.00	0.00	*650.00 F	X
55	1		*FRONT CHASSIS PANEL RHS	0.00	0.00	*650.00 F	X
56	1		*FUSE BOX	0.00	0.00	*150.00 F	7
57	1		*FRONT FENDER LHS	0.00	0.00	*250.00 F	7
58	1		*FRONT FENDER RHS	0.00	0.00	*250.00 F	7
59	1		*FRONT FENDER INNERSHIELD LHS	0.00	0.00	*95.00 F	7
60	1		*FRONT FENDER INNERSHIELD RHS	0.00	0.00	*95.00 F	7
61	1		*FRONT FENDER INNER PANEL LHS	0.00	0.00	*500.00 F	X
62	1		*FRONT FENDER INNER PANEL RHS	0.00	0.00	*500.00 F	X
63	1		*FRONT LOWER CROSSMEMBER ASSY	0.00	0.00	*480.00 F	7
64	1		*FRONT CENTER MEMBER ENGINE MOUNTING	0.00	0.00	*85.00 F	7
65	1		*FRONT DISC ROTOR LHS	0.00	0.00	*155.00 F	7
66	1		*FRONT WHEEL HUB AXLE LHS	0.00	0.00	*120.00 F	7
67	1		*FRONT STEERING KNUCKLE LHS	0.00	0.00	*165.00 F	7
68	1		*FRONT WHEEL BEARING LHS	0.00	0.00	*55.00 F	7
69	1		*FRONT DRIVE SHAFT LHS	0.00	0.00	*580.00 F	7
70	1		*FRONT STABILIZER LINK LHS	0.00	0.00	*65.00 F	7
71	1		*TIE ROD LHS	0.00	0.00	*100.00 F	7
72	1		*TIE ROD END LHS	0.00	0.00	*75.00 F	7
73	1		*FRONT ABSORBER LHS	0.00	0.00	*250.00 F	7
74	1		*FRONT ABSORBER SPRING LHS	0.00	0.00	*190.00 F	7
75	1		*FRONT ABSORBER MOUNTING LHS	0.00	0.00	*75.00 F	7
76	1		*FRONT ABSORBER MOUNTING LHS	0.00	0.00	*160.00 F	7
77	1		*FRONT LOWER ARM LHS	0.00	0.00	*550.00 F	X
78	1		*FRONT BRAKE CALIPER LHS	0.00	0.00	*155.00 F	7
79	1		*FRONT DISC ROTOR RHS	0.00	0.00	*120.00 F	7
80	1		*FRONT WHEEL HUB AXLE RHS	0.00	0.00	*165.00 F	7
81	1		*FRONT STEERING KNUCKLE RHS	0.00	0.00	*55.00 F	7
82	1		*FRONT WHEEL BEARING RHS	0.00	0.00	*580.00 F	7
83	1		*FRONT DRIVE SHAFT RHS	0.00	0.00	*65.00 F	7
84	1		*FRONT STABILIZER LINK RHS	0.00	0.00	*100.00 F	7
85	1		*TIE ROD RHS	0.00	0.00	*75.00 F	7
86	1		*TIE ROD END RHS	0.00	0.00	*250.00 F	7
87	1		*FRONT ABSORBER RHS	0.00	0.00	*190.00 F	7
88	1		*FRONT ABSORBER SPRING RHS	0.00	0.00	*75.00 F	7
89	1		*FRONT ABSORBER MOUNTING RHS	0.00	0.00	*160.00 F	7
90	1		*FRONT LOWER ARM RHS	0.00	0.00	*550.00 F	X
91	1		*FRONT BRAKE CALIPER RHS	0.00	0.00	*450.00 F	7
92	1		*FRONT RIM LHS	0.00	0.00	*450.00 F	7
93	1		*FRONT RIM RHS	0.00	0.00	*250.00 F	7
94	1		*FRONT TYRE LHS	0.00	0.00	*250.00 F	7
95	1		*FRONT TYRE RHS	0.00	0.00	*1,200.00 F	7
96	1		*FRONT WINDSCREEN	0.00	0.00	*75.00 F	7
97	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*250.00 F	7
98	1		*FRONT WINDSCREEN GARNISH CENTER	0.00	0.00	*75.00 F	7
99	1		*FRONT WINDSCREEN GARNISH LHS	0.00	0.00	*75.00 F	7
100	1		*FRONT WINDSCREEN GARNISH RHS	0.00	0.00	*1,200.00 F	X
101	1		*ROOF PANEL	0.00	0.00	*320.00 F	7
102	1		*FRONT A-PILLAR LHS	0.00	0.00	*320.00 F	X
103	1		*FRONT A-PILLAR RHS	0.00	0.00	*320.00 F	X
104	1		*FRONT A-PILLAR TRIM LHS	0.00	0.00	*320.00 F	X
105	1		*FRONT A-PILLAR TRIM RHS	0.00	0.00	*320.00 F	X

Ding Auto Pte Ltd/SJM132R/09/11/2024 12:29. Not valid without Reference section.

Generated using Merlimen e-Claims IEAS

11/9/24, 12:29 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
105	1		*FRONT DOOR LHS	0.00	0.00	*650.00 F	✓
106	1		*FRONT DOOR UPPER HINGE LHS	0.00	0.00	*45.00 F	✓
107	1		*FRONT DOOR LOWER HINGE LHS	0.00	0.00	*45.00 F	✓
108	1		*FRONT DOOR INNER TRIM LHS	CM	0.00	*550.00 F	✓
109	1		*FRONT DOOR HANDLE LHS	nd	0.00	*150.00 F	✓
110	1		*FRONT DOOR LOCK LHS	nd	0.00	*200.00 F	✓
111	1		*FRONT DOOR CATCH	R	0.00	*25.00 F	X
112	1		*FRONT DOOR WEATHERSTRIP LHS	GA	0.00	*120.00 F	✓
113	1		*FRONT WINDOW GLASS LHS	R/R	0.00	*250.00 F	✓
114	1		*FRONT WINDOW FRAME GARNISH UPPER LHS	R/L	0.00	*45.00 F	✓
115	1		*FRONT DOOR PILLAR GARNISH LHS	nd	0.00	*145.00 F	✓
116	1		*FRONT DOOR RHS	R	0.00	*650.00 F	✓
117	1		*FRONT DOOR UPPER HINGE RHS	R	0.00	*45.00 F	✓
118	1		*FRONT DOOR LOWER HINGE RHS	R	0.00	*45.00 F	✓
119	1		*FRONT DOOR INNER TRIM RHS		0.00	*550.00 F	?
120	1		*FRONT DOOR HANDLE RHS	nd	0.00	*155.00 F	X
121	1		*FRONT DOOR LOCK RHS	nd	0.00	*190.00 F	✓
122	1		*FRONT DOOR CATCH RHS	R	0.00	*25.00 F	X
123	1		*FRONT DOOR WEATHERSTRIP RHS		0.00	*120.00 F	?
124	1		*FRONT WINDOW GLASS RHS	R	0.00	*280.00 F	X
125	1		*FRONT WINDOW FRAME WEATHERSTRIP GARNISH RHS		0.00	*55.00 F	?
126	1		*FRONT WINDOW FRAME UPPER GARNISH RHS		0.00	*55.00 F	?
127	1		*FRONT DOOR PILLAR GARNISH RHS		0.00	*155.00 F	?
128	1		*B-PILLAR PANEL LHS		0.00	*420.00 F	?
129	1		*C-PILLAR PANEL LHS		0.00	*350.00 F	?
130	1		*B-PILLAR PANEL RHS	R	0.00	*420.00 F	X
131	1		*C-PILLAR PANEL RHS	R	0.00	*350.00 F	X
132	1		*REAR DOOR LHS	R	0.00	*650.00 F	✓
133	1		*REAR DOOR UPPER HINGE LHS	R	0.00	*45.00 F	✓
134	1		*REAR DOOR LOWER HINGE LHS	R	0.00	*45.00 F	✓
135	1		*REAR DOOR HANDLE LHS	nd	0.00	*45.00 F	✓
136	1		*REAR DOOR INNER TRIM LHS		0.00	*480.00 F	?
137	1		*REAR DOOR WEATHERSTRIP LHS		0.00	*120.00 F	?
138	1		*REAR DOOR GLASS LHS	R	0.00	*250.00 F	X
139	1		*REAR DOOR LOCK LHS	R	0.00	*190.00 F	X
140	1		*REAR DOOR CATCH LHS		0.00	*25.00 F	X
141	1		*REAR WINDOW FRAME WEATHERSTRIP GARNISH LHS	R	0.00	*122.00 F	X
142	1		*REAR DOOR PILLAR GARNISH LHS	R	0.00	*48.00 F	X
143	1		*REAR DOOR FRAME UPPER GARNISH	R	0.00	*48.00 F	X
144	1		*FRONT DOOR WINDOW REGULATOR LHS	R	0.00	*120.00 F	✓
145	1		*FRONT DOOR WINDOW REGULATOR RHS	R	0.00	*120.00 F	✓
146	1		*REAR DOOR WINDOW REGULATOR LHS	R	0.00	*120.00 F	✓
147	1		*FRONT DOOR WINDOW REGULATOR MOTOR LHS	T	0.00	*250.00 F	✓
148	1		*FRONT DOOR WINDOW REGULATOR MOTOR RHS	T	0.00	*250.00 F	✓
149	1		*REAR DOOR WINDOW REGULATOR MOTOR LHS	T	0.00	*250.00 F	✓
150	1		*REAR FENDER LHS	R	0.00	*650.00 F	✓
151	1		*REAR FENDER PANEL LHS	R	0.00	*330.00 F	✓
152	1		*REAR FENDER INNERSHIELD LHS	R	0.00	*45.00 F	X
153	1		*PETROL TANK COVER		0.00	*75.00 F	X
154	1		*REAR RIM LHS		0.00	*450.00 F	?
155	1		*REAR RIM RHS		0.00	*450.00 F	?
156	1		*REAR TYRE LHS		0.00	*250.00 F	?
157	1		*REAR TYRE RHS		0.00	*250.00 F	?
158	1		*REAR BUMPER	R	0.00	*350.00 F	✓
159	1		*REAR TAIL LAMP LHS	CM	0.00	*150.00 F	✓
160	1		*REAR TAIL LAMP RHS	CM	0.00	*150.00 F	✓
161	1		*FRONT SIDE MIRROR LHS	R	0.00	*420.00 F	✓
162	1		*FRONT SIDE MIRROR RHS	R	0.00	*420.00 F	✓
163	1		*FRONT SIDE MIRROR INDICATOR LAMP LHS	R	0.00	*55.00 F	✓

Ding Auto Pte Ltd/SJM132R/09/11/2024 12:29. Not valid without Reference section.

Generated using Merlmen e-Claims IEAS

11/9/24, 12:29 PM

No.	Qty	Part No.	Particulars	Repairer Estimates	%Disc	%Depr	Amount	
164	1		*FRONT SIDE MIRROR INDICATOR LAMP RHS	CMI	0.00	0.00	*55.00 F	✓
165	1		*DASHBOARD ASSY	Tn	0.00	0.00	*550.00 F	✓
166	1		*AIRBAG LHS	ARM	0.00	0.00	*1,250.00 F	✓
167	1		*AIRBAG RHS	~	0.00	0.00	*1,350.00 F	✓
168	1		*AIRBAG ECU	Mc	0.00	0.00	*550.00 F	✓
169	1		*STEERING SPRING COIL	Mc	0.00	0.00	*330.00 F	✓
170	1		*SEAT BELT ASSY LHS	Tn	0.00	0.00	*480.00 F	✓
171	1		*SEAT BELT ASSY RHS	Tn	0.00	0.00	*480.00 F	✓
172	1		*AIRCONT VENT TRIM LHS	NY	0.00	0.00	*95.00 F	✓
173	1		*AIRCONT VENT TRIM RHS		0.00	0.00	*95.00 F	7

F=Franchise part.

Sub Total (S\$)	42,866.00
+ Margin on L,N Items 10.00% (S\$)	4,286.60
Total Parts (S\$)	47,152.60

Ding Auto Pte Ltd/SJM132R/09/11/2024 12:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11/9/24, 12:29 PM

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BUMPER, GRILLE, INNERSHIELD, SEAL AND GARNISH/PANEL - CLIPS	150.00 ✓
2	1	ERP BRACKET STICKER	10.00 ✓
3	1	FRONT NUMBER PLATE AND FRAME	50.00 ✓
4	1	GLUE SEALANT	35.00 ✓
5	1	PRIMER	35.00 ✓
6	1	REFILL - AIRCON GAS	60.00 ✓
7	1	REFILL - COOLANT	60.00 ✓
8	1	WHEEL ALIGNMENT	80.00 ✓
9	1	OD/TP Case (Insurer)	12.00 ✓
Sub Total (\$\$)			492.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	BODY REPAIR, PANEL BEATING & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	2,200.00 ✓
2	SPRAY PAINTING - FRONT BUMPER, FRONT BONNET, FRONT FENDER LHS & RHS, FRONT FOOR LHS & RHS, REAR DOOR LHS, REAR FENDER AND REAR BUMPER	New	2,000.00 ✓
3	REMOVE AND REFIT - FRONT UNDERCARRIAGE COMPONENTS	New	450.00 ✓
4	REMOVE AND REFIT - FRONT DOOR AND REAR DOOR COMPONENTS	New	450.00 ✓
5	REMOVE AND INSTALL - FRONT DOOR WINDOW GLASS	New	200.00 ✓
6	ALIGN HEADLAMP/SIDE MIRROR/DOOR REGULATOR AND CHECK AND TEST WIRING	New	250.00 ✓
7	REMOVE AND REFIT CONDENSER AND RADIATOR COMPONENTS	New	250.00 ✓
8	REMOVE AND REFIT - DASHBOARD COMPONENTS	New	250.00 ✓
9	REMOVE AND REFIT - SEAT BELT (X2) COMPONENTS	New	250.00 ✓
10	REMOVE AND REFIT - FRONT WINDSCREEN GLASS AND MOULDING	New	150.00 ✓
11	AIRBAG ECU AND SENSOR - DIANOSTIC AND RE-PROGRAMMING	New	450.00 ✓
Gross Labour Cost (\$\$)			6,900.00

Ding Auto Pte Ltd/SJM132R/09/11/2024 12:29. Not valid without Reference section.

Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	02/11/2024 10:41 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	29/10/2024 13:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE towards AYE , Near AMK AVE 3 Exit
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM132R
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Boh Chan Nam
NRIC No	SXXXX303J
Email Address	angelinebohsh@gmail.com
Mobile Phone No	(Phone) +65-97661567
Alternative Phone No	+65-96945254

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Allion
Variant	Allion 1.5A
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1497
Vehicle Fuel	Petrol
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	11101659

DRIVER

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Cte to road, MYE, exit AMK av 3.



Witnessed by Reporting Centre Personnel



A: SJM 132R
B: White/blue striped bus



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20241101/7104

2 of 3

Report No. T/20241101/7104

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	BOH CHAN NAM	ID No.	S1305303J
Related Vehicle	SJM132R (Motor car)	Contact No.	96945254
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	29/10/2024	Date Discharge	01/11/2024
No. of Days granted Medical Leave (MC)	46	Degree of Injury	Serious
Passenger			
Name	LAM MOI CHOON	ID No.	S1305308A
Related Vehicle	SJM132R (Motor car)	Contact No.	94362923
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	29/10/2024	Date Discharge	30/10/2024
No. of Days granted Medical Leave (MC)	28	Degree of Injury	Serious
Driver			
Name	Unknown Driver	ID No.	NIL
Related Vehicle	(BUS)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

I am in vehicle number SJM 132 R, travelling at 80km/h on CTE towards AYE, around AMK Ave 3 on Lane 1 (nearest to divider). A white bus on Lane 2, with blue strip side swiped my vehicle hitting my vehicle front passenger door and pushed my vehicle towards the middle barrier. Police and Ambulance arrived at the scene. My wife, Lam Moi Choon, S1305308A and I were injured and sent to Tan Tock Seng hospital via an ambulance. Lam Moi Choon was admitted to hospital with seat belt bruises and airbag injuries. After xray and ct scan, she was subsequently discharged on 30 October. All injuries are documented with Tan Tock Seng. I was also hospitalised with spine fracture and wounds on knees, shoulder and hips. I am discharged from hospital on 1 November 2024, after getting all cleared from doctors.