

AUTO BULLOX PTE LTD

53 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park S(408934)
Tel: 6844 4290 Mobile: 9769 9299 E-Mail: autobullox@gmail.com
Business Reg No: 201919765N

To: Motor Claims Department

Date: 4/11/2024

Vehicle No: GBG9158J

Model: Toyota Hiace

Estimated Repair Cost For GBG9158E

QTY		Amount
1	Rear bumper / BR	\$ 986.70 645/
1	Rear bumper side retainer n/s / BR	\$ 42.00 /
1	Rear bumper brackets n/s X nn	\$ 38.00
1set	Rear bumper clips set / MC	\$ 48.00 30/
1	Taillamp n/s / nn	\$ 496.70 385/
1	Rear side panel n/s X / DD	\$ 1,708.50 /
1	Rear side panel mud flap n/s X nn	\$ 186.50
1	Rear rim n/s X nn	\$ 480.60
1	Rear suspension n/s X nn	\$ 320.50
1	Rear wheel bearing n/s X nn	\$ 296.80
1	Rear axle X nn	\$ 1,796.80
1	Sliding door n/s / DD	\$ 1,468.70 /
1set	Sliding door rubber n/s X nn	\$ 284.60
1	Sliding door bottom latch n/s X nn	\$ 296.70
1	Sliding door top latch n/s X nn	\$ 198.70
1set	Sliding door center latch n/s X nn	\$ 175.60
1	Sliding door inner lock n/s ? x nn	\$ 495.60
1	Sliding door rail n/s X nn	\$ 255.60
1	Rocker panel n/s X nn	\$ 1,068.50

Taillamp lower cover LH / BR \$49

4328.20
-25%
3246.15

Parts Sum: \$ 10,645.10
Parts Less 25%: \$ (2,661.28)
Parts Total: \$ 7,983.82

Special Nett Items

1	Rear side panel sealant / MC	\$ 55.00 30
1	Rear side panel advertisement sticker / MC	\$ 200.00 /
1	Rocker panel sealant X nn	\$ 55.00
1	Sliding door panel sealant / MC	\$ 55.00 30
1	Sliding door panel advertisement sticker / MC	\$ 500.00 400 /
1set	Wheel cap set (Rear LH) / nn	\$ 480.00 120
1	Rear tyre n/s X nn	\$ 450.00

Special Nett Items Total: \$ 1,795.00

780

Labour & Misc Charges

Description	Amount
Labour to remove, renew & align affected accident damaged area @ \$300.00 per day.	\$ 1,500.00 800
Labour to spray painting on affected damage area @ \$300.00 per panel.	\$ 1,500.00 800
To conduct rust proofing on affected panels	\$ 100.00 30
To remove, renew & install sliding door components to facilitate repairs	\$ 150.00 50
To conduct all wheel alignment	\$ 150.00 80
To remove, renew & install rear undercarriage components to facilitate repairs	\$ 300.00 X
To remove & Install reverse sensor and to align the same to specification	\$ 150.00 30
To remove & installed all electrical wiring to facilitate repairs	\$ 80.00 30
To conduct water seepage test	\$ 250.00 X
1820 Labour Charges Total:	\$ 4,180.00

Steve CLKK)
11/11/24, 330pm

m n

L/S

Ly AC 1m
8 days

Parts Total: \$ 7,983.82
Special Nett Items Total: \$ 1,795.00
Labour Charges Total: \$ 4,180.00
Total Cost Of Repair: \$ 13,958.82
(Non-Inclusive of GST)

5846.15

L/S - 4676.92
= 4700

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: