

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110150/EPA3Q2**Date:** 11/04/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230003682
Claimant Vehicle No :	SMJ3930P	Insured Vehicle No :	SLM2112L
Date of Loss:	06/11/2024	Nature of Claim:	TP
		Claim No:	9323017478SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ3930P		
Make & Model:	AUDI A6 DESIGN, 2.0 TFSI (140 KW) (A)	Engine No:	DKY015975
Reg. Date:	28/12/2022 (Man. Year: 2021)	Chassis No:	WAUZZZF26MN098452
Colour:	Blue	Odometer:	7470 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,399.00	588.32	13,810.68	95.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,332.00	3,832.00	2,500.00	39.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,731.00	4,420.32	16,310.68	78.68
+ GST 9.00/9.00% (S\$)	1,865.79	397.83	1,467.96	78.68
Nett Amount (S\$)	22,596.79	4,818.15	17,778.64	78.68
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Medical Costs (S\$)		200.23		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		5,520.56		

INSPECTION

Date of Assignment:	18/11/2024		
Date Inspected:	18/11/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	3,397.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	262.00 FS	*- FS
3	1		*REAR BUMPER SPOILER DARK CHROME MATT	Not Necessary	1,107.00 FS	*- FS
4	2		*REAR BUMPER TRIM LH/RH	Not Necessary	614.00 FS	*- FS
5	1		*REAR BUMPER TRIM CENTER	Not Necessary	215.00 FS	*- FS
6	1		*REAR BUMPER SECURING STRIP	Not Necessary	216.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR LH /RH OUTER	Not Necessary	98.00 FS	*- FS
8	2		*REAR LIGHT REFLECTOR LH /RH INNER	Not Necessary	82.00 FS	*- FS
9	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,232.00 FS	*- FS
10	2		*REAR BUMPER REINFORCEMENT BEAM SEAL LH /RH	Not Necessary	18.00 FS	*- FS
11	2		*REAR BUMPER GUIDE PROFILE LH/RH	Not Necessary	168.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION LH/RH UPPER	Not Necessary	114.00 FS	*- FS
13	1		*REAR BUMPER HOLDING STRAP -CENTER	Not Necessary	149.00 FS	*- FS
14	1		*REAR LID	Repair	4,960.00 FS	*- FS
15	1		*REAR LID PACKING ADHESIVE	Necessary	23.00 FS	*18.32 FS
16	1		*REAR LID ATTACHMENT PARTS	Not Necessary	199.00 FS	*- FS
17	1		*REAR LID LOCK COVER	Not Necessary	9.00 FS	*- FS
18	1		*REAR LID LOCK	Not Necessary	323.00 FS	*- FS
19	1		*AUDI EMBLEM	Necessary	162.00 FS	*129.20 FS
20	1		*A6 EMBLEM	Necessary	116.00 FS	*92.80 FS
21	1		*REAR LID CHROME STRIP -CENTER	Necessary	435.00 FS	*348.00 FS
22	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,399.00** **588.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHT	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID	New	2,200.00	1,100.00
5	TO CARRY OUT CALIBRATION FOR 360 DEGREEEN CAMERA SYSTEM WITH VAS TOOLS	New	800.00	800.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			6,332.00	3,832.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >