

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O in/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: There had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA2259K Yr Regn: 2016 Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit A Hrage C.D. 1193

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 353650 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMB8TA13AFH018851

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim STD A/Rim or

Tyre Size: F: 195/55R15

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / WIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 02/07/24

Survey held at JL Perfect.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Claim 1st Cap.</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>Yes C ✓</u>
	<u>No C)</u>
	<u>MV: 24K</u>
	<u>PV: 10.5K</u>
	<u>Nett: 13.5K</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Form: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

S + P.S. \$ _____

Photos _____

Others _____

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 01.07.2024

TO	:	MS FIRST CAP	MOTOR CLAIMS DEPTS
VEHICLE NO	:	SLA2259K	
MODEL	:	MIT-ATTRAGE	
DATE OF ACCIDENT	:	23.06.2024	
TIME OF ACCIDENT	:	00:00 HOURS	

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL NETT PRICE
1	REAR BUMPER <i>Delnd</i>	1	\$ 708.00	\$ 708.00
2	REAR BUMPER LOWER SPOILER <i>Delnd</i>	1	\$ 1,643.00	\$ 1,643.00
3	REAR BUMPER REFLECTOR <i>ren</i>	2	\$ 20.00	\$ 40.00
4	REAR BUMPER INNER CORNER GARNISH <i>ren</i>	2	\$ 68.00	\$ 136.00
5	REAR BUMPER SIDE RETAINER <i>ren</i>	2	\$ 26.00	\$ 52.00
6	TAIL LAMP <i>ambnd</i>	2	\$ 276.00	\$ 552.00
7	TAIL LAMP PANEL <i>Renr</i>	2	\$ 198.00	\$ 396.00
8	REAR FENDER DRAIN PANEL <i>ren</i>	1	\$ 130.00	\$ 130.00
9	REAR FENDER INNER COWLING <i>ren</i>	2	\$ 45.00	\$ 90.00
10	REAR FENDER INNER TRIM <i>ren</i>	2	\$ 158.00	\$ 316.00
11	BOOT LID <i>Bnelnd</i>	1	\$ 828.00	\$ 828.00
12	BOOT LID SPOILER <i>ren</i>	1	\$ 552.00	\$ 552.00
13	BOOT LID OUTER MOULDING (CHROME) <i>hl</i>	1	\$ 318.00	\$ 318.00
14	BOOT LID LOGO <i>rn</i>	1	\$ 41.00	\$ 41.00
15	BOOT LID HINGE <i>2rn</i>	2	\$ 192.00	\$ 384.00
16	BOOT LID STOPPER <i>rn</i>	4	\$ 19.00	\$ 76.00
17	BOOT LID TOP LOCK <i>rn</i>	1	\$ 206.00	\$ 206.00
18	BOOT LID LOWER LOCK <i>ren</i>	1	\$ 255.00	\$ 255.00
19	BOOT LID WEATHER STRIP <i>at</i>	1	\$ 148.00	\$ 148.00
20	BOOT LID DETECTOR <i>rn</i>	1	\$ 110.00	\$ 110.00
21	BOOT LID DETECTOR WIRE HARNESS <i>ren</i>	1	\$ 385.60	\$ 385.60

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLA2259K**
 MODEL : **MIT-ATTRAGE**
 DATE OF ACCIDENT : 23.06.2024
 TIME OF ACCIDENT : 00:00 HOURS

22	BOOT LID BUZZLE <i>new</i>	1	\$ 95.00	\$ 95.00	+
23	BOOT LID BUZZLE BRACKET <i>new</i>	1	\$ 35.00	\$ 35.00	+
24	REAR END PANEL TOP GARNISH <i>2nd</i>	1	\$ 70.00	\$ 70.00	✓
25	REAR END PANEL <i>Dented</i>	1	\$ 402.00	\$ 402.00	✓
26	REAR END PANEL AIR VENT <i>new</i>	1	\$ 29.00	\$ 29.00	+
27	REAR END PANEL AIR VENT COVER <i>new</i>	1	\$ 39.00	\$ 39.00	+
28	REAR FLOOR PANEL TOP BOARD <i>tom</i>	1	\$ 185.00	\$ 185.00	✓

TOTAL PRICE \$ 8,221.60
 LESS 10% \$ 822.16
SUB TOTAL PRICE \$ 7,399.44

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	RER NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIP (SET) <i>m</i>	1	\$ 80.00	\$ 80.00	30
3	BOOT LID OUTER MOULDING (CHROME) CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
4	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
5	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	✓
6	REAR FENDER INNER COWLING CLIP (SET) <i>gap</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIP (SET) <i>Jan</i>	1	\$ 80.00	\$ 80.00	+
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
10	REVERSE SENSOR (SET) <i>Brand</i>	1	\$ 220.00	\$ 220.00	200
11	REVERSE CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00	+

TOTAL \$ 1,450.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, GRAZE, KNOCK STRAIGHTEN, ADJUST AFFECTED PARTS	\$ 1,800.00	700
2	TO PUTTY, SPRAY PAINT POLISH, WAX	\$ 1,600.00	700

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLA2259K**
 MODEL : **MIT-ATTRAGE**
 DATE OF ACCIDENT : 23.06.2024
 TIME OF ACCIDENT : 00:00 HOURS

3	TO SPRAY TUFF COAT	\$ 250.00	60
4	WIRING, BULB CHECKING	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	60
6	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
9	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	X
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,900.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,849.44
 TOTAL LABOUR COST : \$ 4,900.00
 TOTAL REPAIR COST : \$ 13,749.44

Adrian Cj
2/5 02/07/24
06hys

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: