

# MERIBEL AUTO PTE LTD

Address: 400 ORCHARD ROAD #15-06 (S) 238875

Contact: 83686767

Estimate for SND5580Y (Toyota Alphard)

Not Authorized  
du  
meraj

5 days. 7/11/24

L/S \$ 5800 /  
whph.1. After Upon

|   |            |         |             |   |
|---|------------|---------|-------------|---|
| *TAIL GATE                                | DD/Bent    | 3103.20 | \$3,303.90  | ✓ |
| *TAIL GATE OUTER MOULDING                 | 11         |         | \$590.00    | X |
| *TAIL GATE NUMBER PLATE LAMP              | 11         |         | \$170.00    | X |
| *TAIL GATE LAMP LH                        | 11         |         | \$890.00    | X |
| *TAIL GATE LAMP RH                        | 11         |         | \$890.00    | X |
| *TAIL GATE LOGO                           | 11         |         | \$78.00     | X |
| *TAIL GATE INNER HOLDER                   | 11         |         | \$65.00     | X |
| *TAIL GATE STOPPER                        | 11         |         | \$100.00    | X |
| *TAIL GATE AUTO DAMPER LH/RH              | 11         |         | \$2,240.00  | X |
| *TAIL GATE TOP LOCK                       | Dange      |         | \$450.00    | — |
| *TAIL GATE LOWER LOCK                     | striker 11 |         | \$50.00     | X |
| *TAIL GATE DETECTOR                       | 11         |         | \$380.10    | X |
| *TAIL GATE DETECTOR WIRE HARNESS          | 11         |         | \$595.00    | X |
| *TAIL GATE BUZZER                         | one        |         | \$109.00    | — |
| *TAIL GATE INNER TRIM                     | del/Toon   |         | \$850.10    | — |
| *TAIL GATE WEATHERSTRIP                   | Two        |         | \$365.00    | — |
| *TAIL GATE WINDSCREEN GLASS C/W MOULDING  | 11         |         | \$2,890.00  | X |
| *TAIL LAMP RH                             | 11         |         | \$1,370.20  | X |
| *TAIL LAMP LH                             | 11         |         | \$1,370.20  | X |
| *TAIL LAMP LOWER GARNISH RH               | 11         |         | \$453.20    | X |
| *TAIL LAMP LOWER GARNISH LH               | 11         |         | \$453.20    | X |
| *TAIL LAMP OUTER PANEL                    | 11         |         | \$622.20    | X |
| *TAIL LAMP INNER PANEL                    | 11         |         | \$796.20    | X |
| *REAR FENDER INNER TRIM RH                | 11         |         | \$986.00    | X |
| *REAR FENDER INNER TRIM LH                | 11         |         | \$986.00    | X |
| *REAR BUMPER                              | DD/De      | 1029.30 | \$2,210.24  | — |
| *REAR BUMPER BRACKET x2                   | 11         |         | \$265.60    | X |
| *REAR BUMPER RETAINER (BIG) x2            | 11         |         | \$147.90    | X |
| *REAR BUMPER RETAINER (SMALL) x2          | 11         |         | \$128.70    | X |
| *REAR BUMPER REFLECTOR x2                 | 11         |         | \$141.90    | X |
| *REAR END PANEL                           | DD         |         | \$735.10    | — |
| *REAR END PANEL END EXTEND PANEL          | 11         |         | \$912.20    | X |
| *REAR END PANEL TOP GARNISH               | See        |         | \$285.20    | X |
| *REAR FLOOR PANEL TOP BOARD               | 11         |         | \$870.00    | X |
| *REAR FLOOR PANEL TOP BOARD INNER SUPPORT | 11         |         | \$879.20    | X |
|   |            |         | \$27,629.34 |   |
| Less 25%                                  |            |         | \$6,907.34  |   |
|   |            |         | \$20,722.01 |   |
| *REAR NUMBER PLATE                        | 11         |         | \$50.00     | X |

|       |                                    |     |                   |         |
|-------|------------------------------------|-----|-------------------|---------|
| 1 set | * REAR BUMPER CLIPS                | 111 | \$80.00           | 30 S/W  |
|       | * TAILGATE SEALANT                 | 11  | \$150.00          | X       |
| 1 set | * TAILGATE INNER TRIM CLIP         | 111 | \$80.00           | 30 S/W  |
|       | * TAILGATE WINDSCREEN SOLAR FILM   | 11  | \$550.00          | X       |
|       | * TAILGATE WINDSCREEN SEALANT      | 111 | \$80.00           | 40 S/W  |
|       | * TAILGATE WINDSCREEN INNER SEAL   | 111 | \$60.00           | 20 S/W  |
|       | * TAIL LAMP CLIP                   | 11  | \$30.00           | X       |
|       | * REAR FENDER INNER TRIM CLIP      | 11  | \$80.00           | X       |
|       | * REAR FENDER INNER COWLING CLIP   | 11  | \$80.00           | X       |
|       | * REAR END PANEL INSULATION SEAL   | 11  | \$150.00          | X       |
|       | * REAR FLOOR PANEL INSULATION SEAL | 11  | \$350.00          | X       |
|       | * REAR FLOOR MAT CLIP              | 11  | \$80.00           | X       |
|       | * REVERSE CAMERA                   | 11  | \$600.00          | X       |
| 1 set | * REVERSE SENSOR                   | 11  | \$400.00          | 200 S/W |
|       |                                    |     | <u>\$2,820.00</u> |         |

TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL  
UNITS, RESET MEMORIES TO SPECS

11 \$300.00 X

PANEL BEATING, REMOVAL AND REPLACING OF REAR PARTS  
TO SPRAY PAINT OF REAR AFFECTED AREA

\$1,500.00 800

REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF  
LINING TO FACILITATE REPAIR

\$1,200.00 800

REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING

\$350.00 80

REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING

\$80.00 330

REMOVE AND REFIX TAILGATE WINDSCREEN

\$180.00 120

TRANSFER TAILGATE MECHANISM

\$80.00 60

CONDUCT WATER LEAKAGE TEST

11 \$100.00 X

RUST PROOFING

\$100.00 60

\$3,970.00

Total

\$27,512.01

Date: \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

2- 6641.7  
252  
4981.28  
320  
1950  
7251.28  
22  
5800