



Final Report

Estimate No. : **w5 71708**
Date Estimated : 06/11/2024
Prepared By : Muhammad Salleh Mahmood

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Mohamed Hykal Bin Osman
774 Pasir Ris Street 71
#05-384

- ACCOUNT - 41000
Cash Sales - Svc Motorcycles
PML

Singapore 501774

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FBU40A	WB10L0108N6F7539	28/07/2022	R 1250 RT	39547

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Accident damage repair	975.00	0.00	975.00
Spray painting trim case lid, right	264.00	0.00	264.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH CYLINDER HEAD COVER AGATE GREY	1.00			378.68
SCREW WITH BUSH	3.00			83.70
SET OF GASKETS	1.00			107.12
MODEL LETTERING	1.00			43.20
RH CASE W/O PAINTED PARTS	1.00			583.17
RH TRIM CASE COVER PRIMED	1.00			269.54
BODY SCREW W/O COLLAR M5X20	2.00			16.70
ADDITIONAL HEADLIGHT ADAPTER	1.00			40.55
LED ADDITIONAL HEADLIGHT NANO	1.00			205.68

SUPPLEMENTARY ITEMS

Total Labour :	1,239.00
Total Parts :	1,728.34
Total Labour & Parts :	2,967.34
Deduction for Excess :	
Total Repair Costs less Excess:	2,967.34
GST @9%:	267.06
Grand Total :	3,234.40

Performance Motors Limited.
BMW Motorrad
1 Ubi Road 4, Singapore 408607

Tel: 1800-2255-269
Co Reg No. 197401559W