

Version

Checklist

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Nov 2024)
 Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Charn's Customcraft/SLD8500H/05/11/2024 14:51
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front logo at	0.00	0.00	*36.00 F ✓✓
2	1		*Front logo base cm	0.00	0.00	*65.00 F ✓✓
3	1		*Front bumper top garnish de	0.00	0.00	*185.00 F ✓✓
4	1		*Front bumper cm	0.00	0.00	*550.00 F ✓✓
5	1		*Front bumper towing cover MIS	0.00	0.00	*30.00 F ✓✓
6	1		*Front bumper RHS retainer 7 x nn	0.00	0.00	*25.00 F
7	1		*Front bumper lower spoiler X nn	0.00	0.00	-
8	1		*Front grille cm	0.00	0.00	*135.00 F ✓✓ 364
9	1		*Front grille moulding LHS SLM	0.00	0.00	*140.00 F
10	1		*Front grille moulding RHS SLM	0.00	0.00	*140.00 F
11	1		*Front grille moulding cm (1 set)	0.00	0.00	*370.00 F ✓✓ 364
Sub Total (\$\$)						1,676.00
+ Margin on L,N Items 10.00% (\$\$)						167.60
Total Parts (\$\$)						1,843.60

F=Franchise part.

Charn's Customcraft/SLD8500H/05/11/2024 14:51. Not valid without Reference section.

Generated Using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Front no.plate - S/NETT <i>bf</i>	35.00
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove necessary parts; jacking, panel beating, repair and/or straighten front bonnet, front fenders LHS/RHS inclusive replacing the above.	New <i>4500</i>	600.00
2	Putty and respray front bonnet, front fenders LHS/RHS, front bumper and affected areas.	New <i>600</i>	700.00
Gross Labour Cost (S\$)			1,300.00

Charn's Customcraft/SLD8500H/05/11/2024 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
Hp 9w1w68
5 days
L/S
11/11/24
EXCESS: TBA
Revert
Reay after repair