

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Veron

ECICS Limited

7 Temasek Boulevard
 #10-01 Suntec Tower One
 Singapore 038987
 Tel : 6337 4779
 Fax : 6338 9267

Quotation

DATE : 07.11.2024
 VEH NO : SLC8004D
 MODEL : Mazda 6
 D O A : 05.11.2024
 YR REF : SLA8342M

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8004D (MAZDA 6)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Deformed</i>	1	1,211.90 ✓
2	Front Bumper Side Holder - LH	1	58.90 +
3	Front Bumper Fog Lamp - LH	1	325.50 +
4	Front Bumper Fog Lamp Cover - LH	1	65.10 +
5	Front Bumper Fog Lamp Cover Chrome Moulding - LH	1	70.20 +
6	Head Lamp - LH <i>cut</i>	1	3,259.60 ✓
7	Front Fender - LH <i>Dented</i>	1	485.10 ✓
8	Front Fender Bracket - LH <i>new</i>	1	51.60 +
9	Front Fender Inner Shield - LH <i>ton</i>	1	195.30 ✓
10	Front Lower Arm - LH	1	579.60 +
11	Front Kunkle Arm - LH	1	502.70 +
12	Front Wheel Hub C/W Bearing - LH	1	477.20 +
13	Front Shock Absorber - LH	1	471.90 +
			7,754.60
			Less 20% (1,550.92)
			\$ 6,203.68

5151.90
4121.52

S/NETT ITEMS

1	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
2	Front Wheel Rim - LH <i>cut</i>	1	1,000.00 <i>550</i>
3	Front Tyre - LH <i>new</i>	1	250.00 +
			1,280.00
			\$ 7,483.68

Total Parts

580

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8004D (MAZDA 6)

LABOUR CHARGE

1	To knocking & pull out front LH portion & renew above parts	\$	800.00 500
2	To putty & spray up paint works	\$	600.00 400
3	To check wiring	\$	50.00 30
4	To spray tuff coat	\$	100.00 X
5	To perform wheel alignment	\$	150.00 80
		\$	1,700.00

Grand Total

\$ 9,183.68

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 5711.52
L/s: 4550
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: