

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110159/TVP3M4**Date:** 08/04/2025**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SNJ1020S **Insured Vehicle No :** SMG6110K

Date of Loss: 04/11/2024 Nature of Claim: TP Claim No: DMPC2401500H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNJ1020S**

Make & Model: TOYOTA ALPHARD, 2.5 7-SEATER SR-C (A) Engine No: 2AR2829420

Reg. Date: 22/12/2022 (Man. Year: 2022) Chassis No: AYH300150305

Colour: White Odometer: 63145 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R17 Rear Tyre Size: 225/60R17

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,165.60	1,496.00	9,669.60	86.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,280.00	2,000.00	60.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,445.60	2,776.00	11,669.60	80.78
+ GST 9.00/9.00% (S\$)	1,300.10	249.84	1,050.26	80.78
Nett Amount (S\$)	15,745.70	3,025.84	12,719.86	80.78

INSPECTION

Date of Assignment: 06/11/2024

Date Inspected: 06/02/2025 Inspected At: Diplomat Parts Pte Ltd (HQ)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Apr 2025)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 7-SEATER SR-C (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ1020S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE DOOR	Bent	3,113.60 FS	*990.00 FS
2	1		*REAR TAILGATE GLASS	Not Necessary	1,979.30 FS	*- FS
3	1		*TAILGATE GARNISH	Not Necessary	550.00 FS	*- FS
4	1		*REAR BUMPER	Deformed	961.50 FS	*385.00 FS
5	1		*REAR BUMPER BRACKET	Not Necessary	157.10 FS	*- FS
6	1		*WEATHERSTRIP, BACK TAILGATE	Not Necessary	515.40 FS	*- FS
7	1		*TOYOTA EMBLEM	Necessary	100.20 FS	*66.00 FS
8	1		*ALPHARD EMBLEM	Necessary	94.10 FS	*55.00 FS
9	1		*REAR INNER RHS TAILAMP	Not Necessary	1,642.20 FS	*- FS
10	1		*REAR INNER LHS TAILAMP	Not Necessary	1,642.20 FS	*- FS
11	1		*SOLAR FILM TINT	Not Necessary	280.00 FS	*- FS
12	1		*BODY PNL SEALANT	Not Necessary	50.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					11,165.60	1,496.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR TAILGATE, BUMPER AND DAMAGED PARTS	New	1,200.00	440.00
2	SPRAY RR BUMPER, TAILGATE	New	1,050.00	400.00
3	TO CARRY DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	150.00
4	CHECK WIRING AND ELECTRICAL	New	150.00	50.00
5	RENEW REAR GLASS	New	350.00	120.00
6	SEALING WINDSCREEN	New	120.00	80.00
7	WATER LEAK TEST	New	50.00	0.00
8	ANTI RUST PROOFING	New	80.00	40.00
Gross Labour Cost (\$\$)			3,280.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >