

Performance Motors

BMW Dealer



Supplementary

Estimate No. :
Date Estimated : #####
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Wei Cheong
31 Amber Gardens
#06-03

Singapore 439967

- ACCOUNT -

ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SGV5219E	WBAJA12010BJ2124C	04/07/2019	520i	93822

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To remove PDC assembly, replace damaged parts include reconnecting to bumper and conducting checks for proper function	177.00		177.00 NEQ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour :	177.00
Total Parts :	

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

