



Final Report

Estimate No. :
Date Estimated : #####
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Wei Cheong
31 Amber Gardens
#06-03

Singapore 439967

- ACCOUNT -

ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SGV5219E	WBAJA12010BJ2124C	04/07/2019	520i	93822

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To replacerear bumper panel, rear LH side guide, rear trim strip, rear LH reflector include carrying out other necessary repairs caused by the accident	850.00		850.00
---	--------	--	--------

To spray paint rear bumper	1,038.00		1,038.00
----------------------------	----------	--	----------

To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
---	--------	--	--------

* To remove PDC assembly, replace damaged parts include reconnecting to bumper and conducting checks for proper function	177.00		177.00 NEC✓
--	--------	--	-------------

Sundries	80.00		80.00
----------	-------	--	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

REAR BUMPER LH SIDE GUIDE		1	0.00	203.40
REAR BUMPER TRIM STRIP		1	0.00	82.20
REAR BUMPER PANEL PRIMED (PDC/PMA)		1	0.00	1,731.95
REAR LH REAR REFLECTOR		1	0.00	45.70
DECOUPING RING PDC TORQUE CONVERTER		6	0.00	33.90

SUPPLEMENTARY ITEMS

Total Labour :	2,322.00
Total Parts :	2,097.15
Total Labour & Parts (before GST) :	4,419.15
Deduction for Excess :	
Total Repair Costs less Excess:	4,419.15
GST @9%:	397.72
Grand Total :	4,816.87

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

