



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110161/Uvp3e2
16 RAFFLES QUAY	Date:	20/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 8627Z	Veh. Inspected	SLK 2819S
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24009646MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	07/11/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200 (A)	C.C	1991
Engine No.	26492030497779	Year of Reg.	30/06/2022
Chassis No.	W1K2130802B058624	Colour	BLUE
Odometer	45904 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R18	GOODYEAR	6
L/H Front Tyre	245/45R18	GOODYEAR	6
R/H Rear Tyre	245/45R18	GOODYEAR	6
L/H Rear Tyre	245/45R18	GOODYEAR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/11/2024	Inspection Date	12/11/2024
Survey held at	WE GARAGE - 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days