

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from the Company

11 November 2024

Acknowledged by Repairer

Signature:

Date:

REG NO. : SLK2819S

MAKE/MODEL : MERCEDES BENZ E200

not Authorized

4 days
12/11/24
1/5 \$7500
the photo after repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front Headlamp - RH <i>one</i>	3898.21 \$ 4,895.00 ✓
1	Front Bumper <i>one/torn</i>	1775.50 \$ 2,598.00 ✓
1	Front Bumper Clip (1 Set) <i>new</i>	60.00 \$ 80.00 ✓
1	Front Bumper Inner Sponge <i>torn</i>	\$ 165.00 ✓
1	Front Bumper Reinforcement <i>DD</i>	\$ 696.00 ✓
1	Front Bumper Bracket <i>1/5 one</i>	129.14 \$ 189.00 ✓
1	Front Bumper Side Retainer <i>one</i>	\$ 98.00 ✓
1	Front Bumper Side Grille - RH <i>GVC</i>	\$ 186.00 X
1	Front Bumper Side Moulding - RH <i>cut</i>	\$ 158.00 ✓
1	Front Bumper Chrome Moulding <i>new</i>	\$ 198.00 ✓
2	Front Bumper Side PDC Sensors <i>modification</i>	329.75 \$ 720.00 ✓
1	Front Fender - RH <i>new</i>	\$ 1,680.00 X
1	Front Fender Inner Shield <i>torn</i>	189.55 \$ 197.00 ✓
1	Front Wheel Rim - RH <i>new</i>	\$ 2,880.00 X
1	Front Wheel Hub With Bearing <i>new</i>	\$ 587.98 X
1	Front Shock Absorber <i>new</i>	\$ 727.78 X
1	Front Knuckle Arm <i>new</i>	\$ 1,072.14 X
1	Front Lower Arm <i>new</i>	\$ 1,068.00 X
1	Front Top Arm <i>new</i>	\$ 499.00 X
1	Front Control Arm <i>new</i>	\$ 473.00 X
1	Stabilizer Bar Link <i>new</i>	\$ 97.54 X
		\$ 19,265.44
Less 10%		\$ 1,926.54
		\$ 17,338.90
<u>SPECIAL NETT ITEMS</u>		
1	Front Tyre <i>new</i>	\$ 650.00 X
1	Front Fender Inner Shield Clip (1 Set) <i>new</i>	\$ 120.00 X
1	Wrapping Protection Paint Film (PPF) <i>new</i>	\$ 4,800.00 / 600
		\$ 5,570.00
<u>LABOUR CHARGES</u>		
1	To Check Wiring, Lighting And Resetting Headlamps Focusing	\$ 80.00 20
2	To Remove And Refit Front Sensor	\$ 180.00 X
3	To Remove And Refit Front Undercarriage.	\$ 350.00 X
4	To Remove, Refit And Replaced Damaged Parts	\$ 200.00 X
5	To Conduct Wheel Alignment	\$ 180.00 X
6	To Apply Undercoating.	\$ 180.00 X
7	Panel Beating.	\$ 1,800.00 400
8	To Re-spray Painting On The Affected Areas.	\$ 2,000.00 400
9	To Diagnose Erase Fault Memory After Repair	\$ 600.00 80
		\$ 5,570.00

GRAND TOTAL :

\$ 28,478.90

P- 7697.15

10%

6927.44

1600

900

9427.44

7800