



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24110162/Kvp3e2

Date: 13/11/2024

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8771E	Veh. Inspected	FBL 5460K
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24009730MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	07/11/2024

2. Vehicle Details

Make & Model	YAMAHA FZN150	C.C	149
Engine No.	G3E3E0038592	Year of Reg.	28/10/2016
Chassis No.	ME1RG1611G2001943	Colour	RED
Odometer	151919 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110/70 R17	DUNLOP	2
L/H Front Tyre			
R/H Rear Tyre	180/80 R17	DUNLOP	3
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/11/2024	Inspection Date	08/11/2024
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days